

ASS. REC. BY: Steve CS/C112011262/Emy3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL4512P Yr Regn: 11/2/17
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW 216i c.c. 1499
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 46075 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBA2D920405E91321
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55R17
R: 11

☒ SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>4</u>	mm	R/Bal. <u>4</u>	mm
L/Bal. <u>4</u>	mm	L/Bal. <u>4</u>	mm
D.O.A. <u>28/10/22</u>		D.O.I. <u>10/11/22</u>	
Survey held at <u>Performance</u>			
Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-94K</u>

Order/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Date/Time, File Return to?

☐ : Final Report

Transportation:

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

\$ + RS. \$ _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / L.B.E. (\$) _____

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255249)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 430160
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 63836**
Date Estimated : **28/10/2022**
Prepared By : **Han Kwan Yong**

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -
Wong Tiong Pern (Wang Zhangpeng)
6 bishan street 25 #33-16
#33-16

Singapore 573975

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU5722P	WBA2D920405E91321	07/12/2017	216i G TOURER	43707

DESCRIPTION**VALUE**

To tow accident vehicle to PML workshop.

150.00

To replace front bumper, front center air duct, front left & right support
strut, cross link, right headlight inner support and to knock out dented
are

1709 3,400.00

To respray front bumper and right fender

1876 1,923.00

To replace charge air cooler including conduct check for leak and proper function.

504 531.00

To replace left headlight.

? 481.00

To replace right headlight.

456 481.00

To replace air con condenser and air con hose including
vacuum system, top up freon gas and conduct check for
leak. (For all models except for 7 series).

952

? 1,003.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 177.00

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

168 177.00

To supply front emboss number plate.

78 83.00

Sundries.

150.00

Total Labour 1: **8,556.00**

DESCRIPTION	QTY	PRICE	VALUE
CHARGE AIR COOLER	1	592.55	592.55
RH EXTENSION WHEEL HOUSING STRUT	1	173.00	173.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63836
Date Estimated : 28/10/2022
Prepared By : Han Kwan Yong

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU5722P	WBA2D920405E91321	07/12/2017	216i G TOURER	43707

DESCRIPTION	QTY	PRIC	VALUE
RH CROSS SUPPORT SIDE PANAL ?	1	33.85	33.85
LH VERTIAL STRUT ?	1	49.50	49.50
RH ADAPTER BOTTOM ?	1	82.10	82.10
FRT CROSSLINK ?	1	114.85	114.85
FRT IMPACT ABSORBER ?	1	83.45	83.45
FRT LH BOTTOM DEFORMATION ELEMENT ?	1	91.60	91.60
FRT RH BOTTOM DEFORMATION ELEMENT ?	1	91.60	91.60
FRT BUMPER BOTTOM CARRIER ?	1	156.00	156.00
# FRT FLAP TOWING EYE PRIMED ? CRU	1	43.95	43.95
GRILLE BUMPER MIDDLE CLOSED (PDC) ? CRU	1	121.15	121.15
RH FINISHER (LUXURY LINE) ? BR	1	79.95	79.95
LH ROD ?	1	24.65	24.65
RH ROD ?	1	24.65	24.65
RH SUPPORT FOG LAMP (GESCHLOSSEN) ?	1	80.55	80.55
FRT LH TOP DEFORMATION ELEMENT ?	1	106.75	106.75
FRT RH TOP DEFORMATION ELEMENT ?	1	106.75	106.75
# FRT BUMPER PANEL PRIMED (PMA) ? BR	1	950.80	950.80
RH GRILLE SIDE OPEN (LUXURY LINE+PD) ? BR	1	96.95	96.95
FRT BUMPER TOP CARRIER ?	1	400.80	400.80
RH VERTIAL STRUT ?	1	49.50	49.50
LICENCE PLATE HOLDER ? BR	1	74.50	74.50
FRT LH GRILLE (LUXURY) ?	1	119.35	119.35
FRT RH GRILLE (LUXURY) ? BR	1	119.55	119.55
GROMMET ? BR	2	0.80	1.60
RH SUPPORT HEADLIGHT ARM ?	1	78.50	78.50
LH BOTTOM ADAPTER ?	1	102.30	102.30
MOUNTING WASHER FLUID RESERVOIR ?	1	12.95	12.95
LH SUPPORT ?	1	155.70	155.70
RH SUPPORT ?	1	155.70	155.70
FRONT CROSSLINK ?	1	129.50	129.50
FRONT PANEL V STRUT ?	1	126.80	126.80
# FRT RH WHEEL ARCH COVER ?	1	138.40	138.40
AIR DUCT ?	1	276.05	276.05
UNDERBONNET SCREEN ?	1	191.95	191.95
RH GASKET HEADLIGHT AND HOOD ?	1	19.90	19.90
PLAQUE 82MM ? BR	1	72.85	72.85
FRT ENGINE HOOD SEALING ?	1	52.85	52.85
WASHER FLUID RESERVOIR ?	1	136.80	136.80
LH HEADLIGHT LED TECHNOLOGY ? BR	1	2,399.10	2,399.10
RH HEADLIGHT LED TECHNOLOGY ? BR	1	2,399.10	2,399.10
RH FOG LIGHT ? BR	1	306.85	306.85
CONDENSER AIR CONDITIONING WITH DRI ?	1	1,032.05	1,032.05
ULTRASONIC SENSOR BLACK ?	2	254.05	508.10
DECOUPING RING PDC TORQUE CONVERTER ? BR	2	5.30	10.60

Total Parts : 12,176.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 63836**
Date Estimated : **28/10/2022**
Prepared By : **Han Kwan Yong**

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU5722P	WBA2D920405E91321	07/12/2017	216i G TOURER	43707

Steve (LKK)

10/11/22, 11.00am

OD N/A AL

EXCH-?

P/P

by PL cy
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	8,556.00
Parts	:	12,176.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,461.24
Grand Total	:	22,183.24

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****