

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 21 Nov 2022

Preliminary Advice

Vehicle No	: SLU5722P	Accident Date	: 28/10/2022
Make	: BMW 216D	Policy No.	: DMPCSNW00251392103
Assignment Date	: 09/11/2022	Excess	: S\$500.00
Date of Inspection	: 10/11/2022	Est. Duration of Repair	: 13
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	30,067.05 (inclusive supp: \$9335.05)
Revised Amount	:S\$	20,297.55
Check Items (Estimated)	:S\$	7,897.50
Total	:S\$	28,195.05
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	50,131.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,869.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :kindly approve on supplementary