Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 10 Nov 2022 Jacqueline Tan Date:

Preliminary Advice

Vehicle No : SLU5722P **Accident Date** : 28/10/2022

Policy No. Make : BMW 216D

DMPCSNW00251392103

Assignment Date : 09/11/2022 **Excess** : S\$500.00

Date of Inspection : 10/11/2022 Est. Duration of Repair : 4

: PERFORMANCE MOTORS LIMITED (ALEXANDRA) Inspection At

303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,732.00
Revised Amount	:S\$	9,477.85
Check Items (Estimated)	:S\$	9,382.15
Total	:S\$	18,860.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
D 4 11 11/1	0.0

Pre-Accident Value 94,000.00 :S\$ COE / PARF Rebate :S\$ 50,131.00

Salvage Value :S\$

Margin for Repair :S\$ 43,869.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.	Cindly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to part prices and labour cost check.