

Huey Yon (LKKAUTO)

From: Huey Yon (LKKAUTO)
Sent: Thursday, 24 November 2022 9:15 AM
To: han.kwan.yong@simedarby.com.sg
Cc: SUR
Subject: RE: CHINA-OD SLU 5722P DOA: 15/10/2022
Attachments: SLU 5722P_Supplementary estimate (1).pdf

Dear Han,

Please proceed the supplementary as attached with our surveyor marking.

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>
Sent: Friday, 11 November 2022 9:52 AM
To: han.kwan.yong@simedarby.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: CHINA-OD SLU DOA: 15/10/2022

Dear Han,

As instructed by our client, please proceed to repair the insured vehicle SLU 5722P (**Excess \$500/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933