



Supplementary

Estimate No. : **b1 63836**
Date Estimated : **28/10/2022**
Prepared By : **Han Kwan Yong**

Page No. :

- ESTIMATE REPAIR FOR -

Wong Tiong Pern (Wang Zhangpeng)
6 bishan street 25 #33-16
#33-16

Singapore 573975

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLU5722P	WBA2D920405E91321	07/12/2017	216i G TOURER	46076

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
** To replace front bumper and attachments, washer fluid reservoir, horn, RH fog light, underbonnet screen, front air duct, LH/RH support, RH support headlight arm, RH vertical strut, front RH top deformation element, RH fog lamp support, front RH bottom deformation element, front impact absorber include pulling and straightening on accident areas. To make good the front RH chassis, front RH fender and knocking out dents caused by the accident	5,100.00	0.00	5,100.00 ✓
* To respray front bumper, front RH fender and front RH wheel housing	2,252.00	0.00	2,252.00 ✓
** To conduct chassis measurements using Car-O-Tronic measuring system in accordance with BMW specifications	504.00	0.00	504.00 ✓
** To remove and install engine and auto transmission to facilitate jacking of chassis and mounting of vehicle on car o liner bench include replacement of damaged parts	1,569.00	0.00	1,569.00 ✓
* To check electrical wiring system and lightings include resetting and checking air bags for proper function	280.00	0.00	280.00 ✓
* To remove and install front suspension to facilitate the jacking of chassis and mounting of vehicle on car o liner bench	1009.00	0.00	1009.00 ✓

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W



Performance Motors

BMW Dealer



Supplementary

** To mount vehicle body shell frame on car o liner bench to facilitate the re-alignment of body/chassis in accordance with BMW specifications	2,803.00	0.00	2,803.00	✓
* To reconnect all electrical components and wirings at the front section include conducting checks for proper function	504.00	0.00	504.00	✓
* To remove and install brake discs, brake pads, brake hoses and brake calipers to facilitate repairs include bleeding of brake system, conducting brake tests and checks for leak	953.00	0.00	953.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# BLIND RIVET	0.95	4.00	0.00	3.80	✓ NEC
# EXPANDING NUT	0.85	8.00	0.00	6.80	✓ NEC
# INTAKE SILENCER	462.30	1.00	0.00	462.30	✓ BR
# FRT RH FENDER SEALING	34.55	1.00	0.00	34.55	✓ NEC
# HORN HIGH PITCH	85.35	1.00	0.00	85.35	✓ CRU
# STRAINER FOR WASH PUMP	6.85	1.00	0.00	6.85	✓ NEC

SUPPLEMENTARY ITEMS

Total Labour :	14,974.00
Total Parts :	599.65
Total Labour & Parts (before GST) :	15,573.65

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

