

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 20 Mar 2023

**Preliminary Advice**

Insured Vehicle No	: YN8477K	Accident Date	: 07/11/2022
TP Vehicle No	: SMM9297D	Assignment Date	: 10/11/2022
Make	: MAZDA 6	Est. Duration of Repair	: 3
Date of Inspection	: 05/01/2023		
Inspection At	: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,417.96
Revised Amount	:S\$	3,422.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,422.56
Lump Sum Repair	:S\$	2,700.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.