

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

128

Vehicle: IN / OUT

Date:

Person Contacted:

L74813120

Veh No:

SH 4704J

Yr Regn:

03/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Toyota prius Hybrid 1797

Colour

yellow / black / white

Sp. Reading

699105

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZVW506025164

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/11/22

D.O.I.

10/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt - N/S Body & The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

See serial 02-10-2024

30/11/22 1/5 @ 5900 insured w. 11.11.11

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / i.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s front fender 30.5.20 845	\$ 933.00
02	1 pc	n/s front fender inner cowling 70.11	\$ 172.70
03	1 pc	n/s front fender Hybrid emblem badge n/s	\$ 58.00
04	1 pc	n/s front door 20/12/21 707.50	\$ 1,249.60
05	2 ps	n/s front door hinge @ \$68.00	\$ 136.00
06	1 pc	n/s front door weatherstrip 11	\$ 223.80
07	1 pc	n/s front door side mirror assy 12	\$ 859.80
08	1 pc	n/s front fender quarter garnish 11	\$ 243.30
09	1 pc	n/s front door regulator 11	\$ 230.80
10	1 pc	n/s front door power window motor 11	\$ 768.80
11	1 pc	n/s rocker panel 2	\$ 365.00
12	1 pc	n/s side skirt car/10.11	\$ 872.30
13	1 pc	n/s rear door 30.5.20	\$ 944.00
14	1 pc	n/s rear door weatherstrip 11	\$ 197.40
15	1 pc	n/s rear fender 2	\$ 1,225.50
16	1 pc	rear bumper car	\$ 423.90
17	1 pc	n/s rear fender cowling 11	\$ 198.40
18	6 ps	n/s rear fender cowling clips @ \$4.50 11	\$ 27.00
19	1 pc	n/s rear bumper lower 11	\$ 552.30
20	1 pc	n/s front shock absorber 11	\$ 401.80
21	1 pc	n/s front knuckle arm 30.5.20	\$ 480.00
22	1 pc	n/s front wheel bearing n/s 425	\$ 539.00
23	1 pc	n/s front lower arm 30.5.20	\$ 650.00
24	1 pc	n/s rear door rubber 30.5.20	\$ 222.80
25	1 pc	n/s front door sticker black n/s	\$ 80.00
26	1 pc	n/s rear door sticker black n/s	\$ 80.00
		Less 25 %	\$ 12,135.20
			\$ 3,033.80
			\$ 9,101.40
		<u>SPECIAL NETT ITEMS</u>	
27	2 ps	front wheel rim @ \$400.00 n/s car	\$ 800.00
28	2 ps	rear wheel rim @ \$400.00 2	\$ 800.00
			\$ 1,600.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of left both door fittings and perform water seepage test.	\$ 160.00
02		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 250.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : SHC3154J
Date of Accident : 05 November 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Hang Tau Tee

Date : 07 November 2022

Estimate To Repair SH4704J - Toyota PRIUS HYBRID 1.8S CVT ABS D/A
Chassis No : ZVW506025164

S/No	Quantity	Description	Amount
LABOUR & MISC. CHARGES			
03		To check steering geometry and computer wheel alignment.	\$ 80.00
04		To transfer of tyre, rim and on wheel balancing.	\$ 100.00
05		To check electrical lighting concerned.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00
07		Putty and spray painting of the affected portion.	\$ 1,400.00
			\$ 3,510.00
		Total	\$ 14,211.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6348.5
252
4761.37
300
2320
7381.37
5905