

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

09/11/2022 11:48

OWNER'S PARTICULARS

JOB-NO: 50114620

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3363C

TRANS: AUTO

CHASSIS: JTDKB3FU403092694

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2H18145

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,400.00	0.00	1,400.00	800	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30	Y	
3 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	X	Y	
4 TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	1.00	150.00	0.00	150.00	X	Y	
5 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	200.00	0.00	200.00	30	Y	
6 TO READJUST AND REALIGN HEADLAMP AIM	1.00	120.00	0.00	120.00	30	Y	
7 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	200	Y	
8 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	200	Y	
9 TO RESPRAY FRONT SUPPORT PANEL	1.00	250.00	0.00	250.00	200 100	Y	
10 TO RESPRAY FRONT BUMPER TOWING COVER	1.00	250.00	0.00	250.00	X	Y	
11 TO RESPRAY FRONT LH FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	
12 TO RESPRAY FRONT RH FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	
13 TO RESPRAY FRONT BONNET HINGE	1.00	250.00	0.00	250.00	50	Y	
TOTAL:		4,050.00	0.00	4,050.00			

MATERIALS

1 FRONT BUMPER COVER / BR	1.00	521.00	130.25	390.75	L	Y	
2 FRONT LH BUMPER TOWING COVER X	1.00	30.20	7.55	22.65	L	Y	
3 FRONT BUMPER ENERGY ABSORBER / BR	1.00	80.20	20.05	60.15	L	Y	
4 FRONT BUMPER REINFORCEMENT / BR	1.00	716.60	179.15	537.45	L	Y	
5 RADIATOR GRILLE / BR	1.00	422.50	105.63	316.87	L	Y	
6 RADIATOR GRILLE EMBLEM - BR	1.00	105.80	26.45	79.35	L	Y	
7 RADIATOR GRILLE LOWER NO.1 - (M)	1.00	178.60	44.65	133.95	L	Y	
8 FRONT BUMPER LICENCE PLATE MOULDING	1.00	110.50	27.63	82.87	L	Y	
9 FRONT LH BUMPER RETAINER / BR	1.00	82.30	20.58	61.72	L	Y	
10 FRONT BONNET / BR	1.00	983.10	245.78	737.32	L	Y	
11 FRONT RH BUMPER RETAINER - BR	1.00	80.10	20.03	60.07	L	Y	
12 FRONT LH HEADLAMP - BR	1.00	2,637.60	659.40	1,978.20	L	Y	
13 FRONT RH HEADLAMP - BR	1.00	2,637.60	659.40	1,978.20	L	Y	
14 FRONT BONNET INSULATOR X	1.00	410.90	102.73	308.17	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
15 FRONT LH HEADLAMP PANEL <i>BT</i>	1.00	78.90	19.73	59.17	L	Y	
16 FRONT RH HEADLAMP PANEL <i>BT</i>	1.00	78.90	19.73	59.17	L	Y	
17 RADIATOR GRILLE EMBLEM LOWER COVER	1.00	160.50 <i>BT</i>	40.13	120.37	L	Y	
18 HORN LH <i>X</i>	1.00	134.80	33.70	101.10	L	Y	
19 FRONT BONNET LOCK <i>X</i>	1.00	135.00	33.75	101.25	L	Y	
20 AIR CLEANER INLET NO.3 <i>X</i>	1.00	42.10	10.53	31.57	L	Y	
21 AIR CLEANER INLET NO.2 <i>X</i>	1.00	112.70	28.18	84.52	L	Y	
22 RADIATOR SUPPORT LH SUB-ASSY <i>BT</i>	1.00	245.10	61.28	183.82	L	Y	
23 RADIATOR SUPPORT RH SUB-ASSY	1.00	245.10	61.28	183.82	L	Y	
24 RADIATOR SUPPORT UPPER SUB-ASSY <i>?</i>	1.00	377.10	94.28	282.82	L	Y	
25 A/C CONDENSER <i>?</i>	1.00	1,783.20	445.80	1,337.40	L	Y	
26 FRONT BUMPER UNDERTRAY COVER <i>?</i> (SMALL)	1.00	241.90	60.48	181.42	L	Y	
27 RADIATOR SUPPORT LOWER SUB-ASSY <i>X</i>	1.00	409.90	102.48	307.42	L	Y	
28 FRONT RH BUMPER TOWING COVER <i>X</i>	1.00	30.20	7.55	22.65	L	Y	
29 RADIATOR AIR GUIDE NO.3 <i>X</i>	1.00	112.70	28.18	84.52	L	Y	
30 FRONT BUMPER LOWER ABSORBER <i>X</i>	1.00	132.70	33.18	99.52	L	Y	
31 FRONT LH BONNET HINGE <i>BT</i>	1.00	58.90	14.73	44.17	L	Y	
32 FRONT RH BONNET HINGE <i>BT</i>	1.00	58.90	14.73	44.17	L	Y	
33 FRONT BUMPER CLIP SET <i>MC</i>	1.00	55.00	0.00	55.00	S	Y	
34 FRONT FENDER LINER CLIP SET <i>X</i>	1.00	55.00	0.00	55.00	S	Y	
35 FRONT LICENCE PLATE NUMBER WITH FRAME <i>MC</i>	1.00	80.00	0.00	80.00	S	Y	
36 RADIATOR COOLANT <i>X</i>	1.00	120.00	0.00	120.00	S	Y	
37 FRONT BUMPER ENGINE UNDER COVER CLIP <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
38 FRONT BONNET INSULATOR CLIP SET <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
39 RADIATOR SUPPORT OPENING COVER CLIP SET <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
40 RADIATOR GRILLE CLIP SET <i>MC</i>	1.00	50.00	0.00	50.00	S	Y	
TOTAL:		13,945.60	3,359.00	10,586.60			
Fender emblem LH & RH 2pc <i>\$54.60</i> List <i>MC</i>		17,995.60	3,359.00	14,636.60			
TOTAL PARTS & LABOUR:							

EXCESS/LOADING:\$ 0.00

No. Of Day:

6 days

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY:

1 / 1 /

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX: