

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

09/11/2022 11:48

JOB-NO: 50114620

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

VEHICLE DETAILS

LICENSE NO: SHB3363C TRANS: AUTO
 MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT
 OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: JTDKB3FU403092694
 ENGINE: 2ZR2H18145

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,400.00	0.00	1,400.00	800	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30	Y	_____
3 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	280X	Y	_____
4 TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	1.00	150.00	0.00	150.00	2100X	Y	_____
5 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	200.00	0.00	200.00	30	Y	_____
6 TO READJUST AND REALIGN HEADLAMP AIM	1.00	120.00	0.00	120.00	30	Y	_____
7 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	200	Y	_____
8 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	200	Y	_____
9 TO RESPRAY FRONT SUPPORT PANEL	1.00	250.00	0.00	250.00	200 100	Y	_____
10 TO RESPRAY FRONT BUMPER TOWING COVER	1.00	250.00	0.00	250.00	X	Y	_____
11 TO RESPRAY FRONT LH FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
12 TO RESPRAY FRONT RH FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
13 TO RESPRAY FRONT BONNET HINGE	1.00	250.00	0.00	250.00	50	Y	_____
TOTAL:		4,050.00	0.00	4,050.00			_____

MATERIALS

1 FRONT BUMPER COVER / BR	1.00	521.00	130.25	390.75	/	L	Y	_____
2 FRONT LH BUMPER TOWING COVER X AN	1.00	30.20	7.55	22.65	/	L	Y	_____
3 FRONT BUMPER ENERGY ABSORBER / BR	1.00	80.20	20.05	60.15	/	L	Y	_____
4 FRONT BUMPER REINFORCEMENT / AN	1.00	716.60	179.15	537.45	/	L	Y	_____
5 RADIATOR GRILLE / BR	1.00	422.50	105.63	316.87	/	L	Y	_____
6 RADIATOR GRILLE EMBLEM - BR	1.00	105.80	26.45	79.35	/	L	Y	_____
7 RADIATOR GRILLE LOWER NO.1 - (M)	1.00	178.60	44.65	133.95	/	L	Y	_____
8 FRONT BUMPER LICENCE PLATE MOULDING	1.00	110.50	27.63	82.87	/	L	Y	_____
9 FRONT LH BUMPER RETAINER / BR	1.00	82.30	20.58	61.72	/	L	Y	_____
10 FRONT BONNET - AN	1.00	983.10	245.78	737.32	/	L	Y	_____
11 FRONT RH BUMPER RETAINER - BR	1.00	80.10	20.03	60.07	/	L	Y	_____
12 FRONT LH HEADLAMP - BR	1.00	2,637.60	659.40	1,978.20	/	L	Y	_____
13 FRONT RH HEADLAMP - BR	1.00	2,637.60	659.40	1,978.20	/	L	Y	_____
14 FRONT BONNET INSULATOR X AN	1.00	410.90	102.73	308.17	/	L	Y	_____

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
15 FRONT LH HEADLAMP PANEL	1.00	78.90	19.73	59.17	L	Y	
16 FRONT RH HEADLAMP PANEL	1.00	78.90	19.73	59.17	L	Y	
17 RADIATOR GRILLE EMBLEM LOWER COVER	1.00	160.50	40.13	120.37	L	Y	
18 HORN LH	1.00	134.80	33.70	101.10	L	Y	
19 FRONT BONNET LOCK	1.00	135.00	33.75	101.25	L	Y	
20 AIR CLEANER INLET NO.3	1.00	42.10	10.53	31.57	L	Y	
21 AIR CLEANER INLET NO.2	1.00	112.70	28.18	84.52	L	Y	
22 RADIATOR SUPPORT LH SUB-ASSY	1.00	245.10	61.28	183.82	L	Y	
23 RADIATOR SUPPORT RH SUB-ASSY	1.00	245.10	61.28	183.82	L	Y	
24 RADIATOR SUPPORT UPPER SUB-ASSY	1.00	377.10	94.28	282.82	L	Y	
25 A/C CONDENSER	1.00	1,783.20	445.80	1,337.40	L	Y	
26 FRONT BUMPER UNDERTRAY COVER	1.00	241.90	60.48	181.42	L	Y	
(SMALL)							
27 RADIATOR SUPPORT LOWER SUB-ASSY	1.00	409.90	102.48	307.42	L	Y	
28 FRONT RH BUMPER TOWING COVER	1.00	30.20	7.55	22.65	L	Y	
29 RADIATOR AIR GUIDE NO.3	1.00	112.70	28.18	84.52	L	Y	
30 FRONT BUMPER LOWER ABSORBER	1.00	132.70	33.18	99.52	L	Y	
31 FRONT LH BONNET HINGE	1.00	58.90	14.73	44.17	L	Y	
32 FRONT RH BONNET HINGE	1.00	58.90	14.73	44.17	L	Y	
33 FRONT BUMPER CLIP SET	1.00	55.00	0.00	55.00	S	Y	
34 FRONT FENDER LINER CLIP SET	1.00	55.00	0.00	55.00	S	Y	
35 FRONT LICENCE PLATE NUMBER WITH FRAME	1.00	80.00	0.00	80.00	S	Y	
36 RADIATOR COOLANT	1.00	120.00	0.00	120.00	S	Y	
37 FRONT BUMPER ENGINE UNDER COVER	1.00	50.00	0.00	50.00	S	Y	
CLIP							
38 FRONT BONNET INSULATOR CLIP SET	1.00	50.00	0.00	50.00	S	Y	
39 RADIATOR SUPPORT OPENING COVER CLIP SET	1.00	50.00	0.00	50.00	S	Y	
40 RADIATOR GRILLE CLIP SET	1.00	50.00	0.00	50.00	S	Y	
TOTAL:		13,945.60	3,359.00	10,586.60			
Fender emblem LH & RH 2pc		17,995.60	3,359.00	14,636.60			

TOTAL PARTS & LABOUR :

EXCESS/LOADING:\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00