

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJN8603R

Accident Date : 05-Nov-2022

Our Ref : 022184 (CHINA) / CHAN

KOH CHEE TIONG
BLK 538 ANG MO KIO AVE 5
#07-4008
Singapore 560538

No. : 06691

Date : 08-Nov-2022

PAGE : 1

Not Notion
Resurvey B4 pain
8 days
11 Pny & 5400.

ESTIMATED COST OF REPAIR FOR TOYOTA FREED HYBRID SMP5953D

- 1 pc Tail gate
- 1 pc Tail gate glass moulding
- 1 pc Tail gate "FREED" emblem
- 1 pc Tail gate logo
- 1 pc Tail gate "HYBRID" emblem
- 1 pc Tail gate inner lock
- 1 pc Tail gate open pocket
- 1 pc Tail gate rubber
- 1 pc Tail gate outer chrome
- 1 pc Rear end panel
- 1 pc End panel top garnish
- 1 pc Rear spare tyr panel
- 1 pc Rear bumper fascia

Bz 1,100.00 ✓
na 86.40 ✓
na 55.00 ✓
na 38.50 ✓
na 75.00 ✓
na 92.50 ✓
na 25.00 ✓
Dir/Kt 168.00 ✓
sn 280.00 X
Bz 423.70 ✓
na 115.00 ✓
Bz 1,056.00 ✓
Bz 950.00 ✓

4,465.10

Less 20% : 893.02

- 1 pc Tail gate auto damaper
- 1 pc Rear bumper reverse sensor(set)
- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper clip (set)
- 1 pc Rear no.plate with casing

Pre/Km 3,572.08 ✓
sn 1,200.00 sn ✓
sn 300.00 sn X
na 60.00 sn ✓
na 30.00 sn ✓
sn 50.00 sn X

To remove & refix rear windscreen
glass and conduct water leak test.

120/
150.00

LKK Auto Consultants hence notify
the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Con't Page 2 ...

EF: C12/2201-01-11

Aspire 3

A314-32-C6Z5



ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJN8603R

Page : 2

To remove roof lining, front and rear seats, trim board and carpet	120.00	901
To apply undersealing	100.00	901
To putty and spray replaced parts	1,000.00	8001
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,200.00	11001
Total :	S\$ 7,782.08	

Singapore Dollars Seven Thousand Seven Hundred and Eighty Two and Cents Eight Only