

ASS. REC. BY:

REF:

09/CT/2011293/Any3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKJ1107L Yr Regn: 2021 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 c.c. 1395Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 17143 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ2F31M1131647Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModif: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/65R17R: 215/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/11/22Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP China</u>
	<u>Adrian confirmed final fig \$ 17624.60, and 5 days</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?



: Preli. Report

1) 17/1/23

: Final Report

Date/Time, File Return to?

2) _____

- Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Photos

: Onsite

Report Format: TP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0977/2022/EQ
DATE : 8-Nov-22
WIP : 49627

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PHUA SWEE ANN
ADDRESS : BLK 579 WOODLANDS DRIVE 16
#07-598
SINGAPORE 730579
TELEPHONE : HP +65 93828375
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210139363
VEHICLE NO : **SKJ 1107 L**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 19/11/2021
ENGINE NO : CZD C41890
CHASSIS NO : WAUZZZF31M1131647
MILEAGE : 17,143
DATE IN : 8-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Nov-22
PLACE OF ACCIDENT : 60 JLN PENJARA, SINGAPORE 149375

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 1107 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	✓
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1800 ✓
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 5,000.00	2900 ✓
TOTAL LABOUR CHARGES		: \$ 9,480.00	$3 \times 800 = 2400$ $\text{Wheel Arc} \times 2 = 500$ <u>2900</u>

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 1107 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 9,952.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 1107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deled</i>	1	\$ 2,018.00	<i>/</i>
2	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	1	\$ 66.00	<i>+</i>
3	FRONT BUMPER TRIM <i>new</i>	1	\$ 396.00	<i>? X</i>
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 242.00	<i>+</i>
5	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 58.00	<i>+</i>
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 212.00	<i>+</i>
7	FRONT BUMPER SPOILER <i>Debond</i>	1	\$ 850.00	<i>? 849.50 ✓</i>
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 171.00	<i>+</i>
9	FRONT BUMPER TRIM - RH <i>new</i>	1	\$ 182.00	<i>? X</i>
10	FRONT PARKING AID SENSOR SUPPORT - RH <i>new</i>	1	\$ 29.00	<i>+</i>
11	RADIATOR GRILLE <i>new</i>	1	\$ 2,135.00	<i>X</i>
12	RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$ 271.00	<i>X</i>
13	RADIATOR GRILLE COVER <i>new</i>	1	\$ 271.00	<i>+</i>
14	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 43.00	<i>? X</i>
15	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 114.00	<i>+</i>
16	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 974.00	<i>+</i>
17	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 137.00	<i>+</i>
18	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	<i>+</i>
19	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	<i>+</i>
20	FRONT FENDER - RH <i>Deled</i>	1	\$ 1,445.00	<i>/</i>
SUB TOTAL SPARE PARTS		:	\$ 9,639.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 1107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 66.00	+
22	FRONT FENDER BRACE - RH <i>Revised</i>	1	\$ 98.00	> 97.10 ✓
23	FRONT FENDER BRACKET - RH <i>new</i>	1	\$ 39.00	? X
24	FRONT FENDER CLOSING ELEMENT - RH <i>new</i>	1	\$ 37.00	? X
25	FRONT WHEEL HOUSING LINER - RH	1	\$ 260.00	+
26	FRONT WHEEL HOUSING LINER COVER - RH <i>new</i>	1	\$ 18.00	+
27	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 22.00	+
28	FRONT PARKING AID SENSOR	1	\$ 266.00	+
29	FRONT PARKING AID SEAL RING	4	\$ 10.00	+
30	HEADLIGHT MOUNTING - RH <i>new</i>	1	\$ 132.00	> X
31	HEADLIGHT - RH <i>cracked</i>	1	\$ 5,952.00	✓
32	LIFT CYLINDER - RH <i>new</i>	1	\$ 231.00	+
33	LIFT CYLINDER HOSE	1	\$ 92.00	+
34	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 1,132.00	✓ 1131
35	RADIATOR AIR GUIDE - RH <i>new</i>	1	\$ 43.00	+
36	FRONT DOOR - RH <i>Revised</i>	1	\$ 3,028.00	+
37	FRONT OUTER DOOR SEAL - RH	1	\$ 185.00	+
38	FRONT DOOR CATCH	1	\$ 134.00	+
39	FRONT DOOR COVER - RH	1	\$ 390.00	+
40	FRONT WINDOW SLOT SEAL TRIM STRIP - RH OUTER <i>new</i>	1	\$ 251.00	+
SUB TOTAL SPARE PARTS			\$ 12,386.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 1107 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT NO PLATE <i>He m</i>	S/N	\$	60.00	<i>x</i>
42	SUNDRIES <i>He m</i>		\$	800.00	<i>?x</i>
TOTAL SPARE PARTS		:	\$	22,885.00	
TOTAL LABOUR CHARGES		:	\$	9,952.00	
GRAND TOTAL		:	\$	32,837.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *10/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT