



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: Allianz Insurance Singapore Pte. Ltd.
COMPANY NAME: Allianz Insurance Singapore Pte. Ltd.
STREET ADDRESS: 79 Robinson Road, #09-01
POSTAL CODE: Singapore 068897
PHONE: 6714 3369

DATE: 9/11/2022
REF: 6K56944G
VEHICLE NO.: 8K56944G
MAKE: BMW
MODEL: 2181
PREPARED BY: MR POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REFIT TAIL LAMP & WIRING AND TEST FOR PROPER FUNCTIONING	1		\$80.00	\$ 80.00	mx	\$ 80.00
2	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST FOR REPAIR	1		\$200.00	\$ 200.00	30	\$ 200.00
3	TO REMOVE & REFIT ALL DAMAGED PARTS & PANELS AND REALIGN	1		\$400.00	\$ 400.00	200	\$ 400.00
4	TO PAINT ALL NEW PARTS & PANELS	1		\$400.00	\$ 400.00	300	\$ 400.00
PARTS							
1	REAR BUMPER	1		\$1,368.00	\$ 1,368.00	x R	\$ 1,368.00
2	REAR BUMPER CLIPS	10		\$5.00	\$ 50.00	mx	\$ 50.00
3	REAR BUMPER RH RETAINER	1		\$247.00	\$ 247.00	mx	\$ 247.00
4	RIGHT TAIL LAMP	1		\$494.00	\$ 494.00	mx	\$ 494.00
5	REAR RH FENDER - REPAIR						494
6	REAR RF DOOR - REPAIR						10% 444.60
SUBTOTAL					\$ 3,239.00	SUBTOTAL	\$ 3,239.00
GST 7%					\$ 226.73	GST 7%	\$ 226.73
TOTAL					\$ 3,465.73	TOTAL	\$ 3,465.73

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to the vehicle
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

FOR DICKSON AUTO CARE CENTRE PTE LTD

(AUTHORISED SIGNATURE)



confirmed
16/4/2023