



**DICKSON GROUP**  
Your Trusted Automotive Solutionist

**DICKSON AUTO CARE CENTRE PTE LTD**  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

## QUOTATION

### QUOTATION FOR

**NAME:** Allianz Insurance Singapore Pte. Ltd.  
**COMPANY NAME:** Allianz Insurance Singapore Pte. Ltd.  
**STREET ADDRESS:** 79 Robinson Road, #09-01  
**POSTAL CODE:** Singapore 068897  
**PHONE:** 6714 3369

**DATE:** 9/11/2022

**REF:** SKS6944G  
**VEHICLE NO.:** SKS6944G  
**MAKE:** BMW  
**MODEL:** 2181  
**PREPARED BY:** MR POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<b>LABOUR</b>						
1	TO REMOVE & REFIT TAIL LAMP & WIRING AND TEST FOR PROPER FUNCTIONING	1		\$80.00	\$ 80.00		\$ 80.00
2	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST FOR REPAIR	1		\$200.00	\$ 200.00		\$ 200.00
3	TO REMOVE & REFIT ALL DAMAGED PARTS & PANELS AND REALIGN	1		\$400.00	\$ 400.00		\$ 400.00
4	TO PAINT ALL NEW PARTS & PANELS	1		\$400.00	\$ 400.00		\$ 400.00
	<b>PARTS</b>						
1	REAR BUMPER	1		\$1,368.00	\$ 1,368.00		\$ 1,368.00
2	REAR BUMPER CLIPS	10		\$5.00	\$ 50.00		\$ 50.00
3	REAR BUMPER RH RETAINER	1		\$247.00	\$ 247.00		\$ 247.00
4	RIGHT TAIL LAMP	1		\$494.00	\$ 494.00		\$ 494.00
5	REAR RH FENDER - REPAIR						
6	REAR RF DOOR - REPAIR						

### REMARKS:

<b>SUBTOTAL</b>	\$ 3,239.00	<b>SUBTOTAL</b>	\$ 3,239.00
<b>GST 7%</b>	\$ 226.73	<b>GST 7%</b>	\$ 226.73
<b>TOTAL</b>	\$ 3,465.73	<b>TOTAL</b>	\$ 3,465.73

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND  
COMPANY STAMP)

(AUTHORISED SIGNATURE)

