

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

7P 1st Cap.
Xin Yu

MRO53REH104518885

ESTIMATE OF REPAIR

Veh# : SKQ6604Z

Model: TOYOTA COROLLA ALTIS

Accident Date : 9/11/22

18/12/2014

Location : ADMIRALTY WEST ROAD

3P: SMS6855G (1ST CAP)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Delint</i>	681.40	✓ 581.40	
2	10pcs	Rear bumper clips <i>in</i>		30.00	✓
3	2pcs	Rear bumper screw clips <i>in</i>	35	30 20.00	✓
4	1pc	Rear bumper enforcement <i>Dented</i>	451.40	✓	
5	2pcs	Rear bumper enforcement o/s & n/s bracket <i>As intro</i>	262.70	(131.35)	✓
6	2pcs	Rear bumper o/s & n/s reflector <i>new</i>	275.40	X	
7	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	162.70	81.35	
8	2pcs	Rear reverse sensor <i>new</i>		380.00	new/en
9	2pcs	Rear reverse sensor wire harness <i>new</i>		180.00	X
10	1pc	Rear reverse camera <i>new</i>		680.00	X
11	1pc	Rear end panel <i>new</i>	881.90	X	
12	1pc	Rear end panel inner trim <i>new</i>	453.50	X	
13	4pcs	Rear end panel inner trim clips <i>new</i>		16.00	X
14	2pcs	Rear o/s & n/s tail lamp <i>new</i>	878.20	X	
15	2pcs	Rear o/s & n/s tail lamp retainer <i>new</i>	280.30	X	
16	1pc	Rear boot cover <i>Breached</i>	1,174.40	781.10	
17	1pc	Rear boot cover weatherstrip <i>new</i>	274.40	X	
18	1pc	Rear boot cover emblem <i>new</i>	61.50	✓	
19	1pc	Rear boot cover 'COROLLA' emblem <i>new</i>	61.70	✓	
20	1pc	Rear boot cover 'ALTIS' emblem <i>new</i>	67.70	✓	
21	2pcs	Rear boot cover o/s & n/s hinges <i>new</i>	464.50	X	
22	1pc	Rear boot cover moulding <i>new</i>	387.10	X	
23	4pcs	Rear boot cover moulding clips <i>new</i>		16.00	X
24	1pc	Rear boot cover moulding chrome <i>new</i>	385.50	X	
25	4pcs	Rear boot cover moulding chrome clips <i>new</i>		16.00	X
26	1pc	Rear boot cover lock (Upper) <i>new</i>	291.60	✓	
27	1pc	Rear boot cover lock (Lower) <i>new</i>	43.10	X	
28	2 pcs	Rear boot cover o/s & n/s reflector <i>new</i>	652.50	X	
Sub Total:			8,191.50	1338.00	0.00
			25%	0%	10%
After Less %:			6,143.63	1338.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	800.00	500	
2		To spray painting.	600.00	600	
3		To remove and replace rear tail gate	80.00	X	
4		To remove and replace rear reverse sensor	80.00	50	
5		To check wiring.	100.00	30	
6		To re seal anti rust.	100.00	40	
Sub Total:			1,760.00		
Total:			9,241.63		
After Less 20%:			7,393.30		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No later modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Chan San Choon
Director
DipEng, AAE(MIM),MSAE(Aust)

Acknowledged by Repairer

Signature:

Signature: *bigSAFE* 8778 1999

Mobil 1

24 h SKQ6604Z ESTIMATE Pg1



PAYNOW

2457.20

1842.80

SN: 250

1220

Adm L

4/5 11/11/22

040 days.

total: 3312.80

4/5: 2650