



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011298/Evy3e2	
			Date: 11/01/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 366P	Veh. Inspected	SNF 1019T
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/22/2086	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	10/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	W1K2060412R032315	Colour	BLUE
	Odometer	8241 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R21	DUNLOP	4 mm
	L/H Front Tyre	225/50 R21	DUNLOP	4 mm
	R/H Rear Tyre	225/50 R21	DUNLOP	4 mm
	L/H Rear Tyre	225/50 R21	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2022	Inspection Date	14/11/2022
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	