



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 194409367N
GST Reg No. MR 85691117

ESTIMATE FOR SNF1019T

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No 60569
Reg No/Reg Date SNF1019T / 29/04/2022
Date In/Mileage / 0
Chassis No W1K2060412R0323159
Engine No 254915V0032719
Make/Model MB/C 180
Colour/Trim 028 890 Cavansite B/ 041 104 Leather Sie

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	14/11/2022/ 09:23	VS	356 / Vincent Seah			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 7220047339 // 27.10.2022

DRIVE IN/EXCESS : 27.10.2022 // TP CAR NO.: SHB366P=FIRST CAPITAL

DATE IN/DATE SURVEY: 14.11.2022//

DIRECT SETTLEMENT: Ana Magnaye// STRIDES AUTOMOTIVE

M BPNSUN

SUNDRIES

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

PANEL BEAT TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA

S BPNSUB

SUPPLY 1 SET NUMBER PLATE WITH HOUSING-NETT CUT

M FRONT BUMPER

X R

AIR DUCT SEGMENT

LICENSE PLATE HOLDER

RAD. CHROME TRIM

RAD. PROTECTIVE GRILLE

BASE PLATE STAR

RAD. GRILLE CARRIER

1.00	1432.04	00.00	1432.04
1.00	133.70	00.00	133.70
1.00	134.42	00.00	134.42
1.00	274.53	00.00	274.53 ✓
1.00	142.12	00.00	142.12
1.00	467.63	00.00	467.63
1.00	222.95	00.00	222.95

L&K Auto Consultants hence notify

the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

Parts used are subject to confirmation

Confirmed & accepted by

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Authorized signature and company stamp

Signature:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 1 of 1