



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNF1019T

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 60569
Reg No/Reg Date SNF1019T / 29/04/2022
Date In/Mileage 14/11/2022/ 8241
Chassis No W1K2060412R0323159
Engine No 254915V0032719
Make/Model MB/C 180
Colour/Trim 028 890 Cavansite B/ 041 104 Leather Sie

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	10/01/2023/ 10:29	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
M BPNSUN POLICY NO/ACC DATE :7220047339 // 27.10.2022 DRIVE IN/EXCESS : 27.10.2022 // TP CAR NO.: SHB366P=FIRST CAPITAL DATE IN/DATE SURVEY:14.11.2022// 14.11.2022 STEVE-LKK 11:15AM DIRECT SETTLEMENT:Ana Magnaye// STRIDES AUTOMOTIVE				15.00
M BPNSUN SUNDRIES		0.10		380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				960.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		0.05		800.00
A BPIRES RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA				60.00
S BPNSUB SUPPLY 1 PC NUMBER PLATE WITH HOUSING-NETT FRONT				
X RAD. CHROME TRIM	1.00	274.53	00.00	274.53

Finalization

3 days

Confirmed & accepted by

Nett 2,489.53
8% GST on 2489.53 199.16
Total Payable 2,688.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG