

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 11 Nov 2022

Preliminary Advice

Vehicle No	: XE4435S	Accident Date	: 03/11/2022
Make	: MAN TGS 26.320 6X4 BB	Policy No.	: 202222007884/FR
Assignment Date	: 10/11/2022	Excess	: S\$4,500.00
Date of Inspection	: 11/11/2022	Est. Duration of Repair	: 5
Inspection At	: ST ENGINEERING LAND SYSTEMS LTD (HQ) 31 CORPORATION ROAD SINGAPORE 649825		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,511.83
Revised Amount	:S\$	2,286.41
Check Items (Estimated)	:S\$	8,225.42
Total	:S\$	10,511.83

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 130,000.00
COE / PARF Rebate	:S\$ 15,907.00
Salvage Value	:S\$

Margin for Repair

:S\$ 114,093.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.