



NXPRESS PERFORMANCE PTE. LTD.

SYNERGY @ KB, 25, KAKI BUKIT ROAD 4, #01-39, SINGAPORE 417800

CONTACT: (65) 8127 0834/ (65) 9730 4896

EMAIL: NXPRESS18@GMAIL.COM

CO. REGISTRATION NO: 201802554E

INVOICE

Claimant: M/s. Ace95 Car Rental Pte Ltd

Date of Invoice : 09/02/2022

C/o. M/s. Nxpress Performance Pte. Ltd.

25 Kaki Bukit Road 4

Synergy@KB #01-39

Singapore 417800

Claim Type : Third Party

Date of Accident : 13/01/2022

Vehicle Reg. No : SJN6670J

Vehicle Make/Model : Mitsubishi Lancer (A) GLX

Description	Amount (S\$)
Lump Sum Repairs As Per Recommendation.	\$ 3,190.00
Total	\$ 3,190.00
Singapore Dollar : Three Thousand One Hundred Ninety Dollars Only.	



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

INVOICE

To. M/s. Ace95 Car Rental Pte Ltd
C/o. 25 Kaki Bukit Road 4
Synergy@KB #01-39
Singapore 417800

Invoice No. : HA/2202-09

Date : 08/02/2022


Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 430.00
SGD Dollar : Four Hundred Thirty Dollars Only.	
Our Reference : PAS/TP/0190122	
Vehicle No. : SJN6670J	
Make & Model : Mitsubishi Lancer (A) GLX	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0190122

Date of Report : 08/02/2022

To : M/s. Ace95 Car Rental Pte Ltd
C/o. 25 Kaki Bukit Road 4
Synergy@KB #01-39
Singapore 417800

Date of Assignment : 14/01/2022
Report requested by : M/s. Ace95 Car Rental Pte Ltd
Date of Accident : 13/01/2022
Date of Inspection : 14/01/2022
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJN6670J
Make & Model : Mitsubishi Lancer (A) GLX
Date of Registration : 25/02/2009
Colour : Met. Blue

Engine Capacity (cc) : 1584cc
Mileage (km) : 165565km
Chassis / Frame No. : JMYSTCS3A9U004065
Engine No. : 4G18KB1777

TYRE CONDITION

Front LH : 6 mm
Make : Triangle

Front RH : 6 mm
Make : Triangle

Rear LH : 6 mm
Make : Dunlop

Rear RH : 6 mm
Make : Dunlop

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Nxpress Performance Pte Ltd
25, Kaki Bukit Road 4, Synergy@KB, #01-39, Singapore 417800

ASSESSMENT

Repairer's Estimate : \$ 5,699.36
Revised Amount : \$ 3,992.46
Less Excess : \$ -
Recommended Reserve : \$ 3,190.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJN6670J

Report No. : PAS/TP/0190122

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Nxpress Performance Pte Ltd, 25, Kaki Bukit Road 4, Synergy@KB, #01-39, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The bonnet, front support panel, front chassis members, front bumper, RHF fender, front grilles, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$3,992.46.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,190.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 2014044340

Vehicle No : SJN6670J

Report No. : PAS/TP/0190122

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$)	Our Assessment (\$)
1	1 pc	Bonnet	Dented/Distorted	\$ 629.00	\$ 629.00 ✓
2	1 pc	Bonnet lock	Serviceable	\$ 46.00	\$ 50 ✓
3	1 pc	Headlamp RH	Refit	\$ 539.00	\$ X ✓
4	2 pcs	Frt grille R/L	Dented/Cracked	\$ 176.00	\$ 176.00 ✓
5	6 pcs	Frt grille clip	Necessary	\$ 14.40	\$ 14.40 ✓
6	1 pc	Frt grille garnish	Dented/Cracked	\$ 142.00	\$ 142.00 90 ✓
7	1 pc	Frt emblem	Necessary	\$ 37.00	\$ 37.00 ✓
8	1 pc	Frt bumper	Dented	\$ 718.00	\$ 718.00 530 ✓
9	1 pc	Frt no.plate garnish	Dented/Deformed	\$ 35.00	\$ 35.00 ✓
10	1 pc	Frt bumper air dam (Skirt)	Refit	\$ 656.00	\$ X ✓
11	10 pcs	Frt bumper rivet	Necessary	\$ 20.00	\$ 20.00 ✓
12	2 pcs	Frt bumper side retainer R/L	Dented/Necessary	\$ 82.00	\$ 82.00 45 ✓
13	1 pc	Frt support panel assy	Dented/Distorted	\$ 616.00	\$ 616.00 R ✓
14	1 pc	Frt fender RH	Dented/Repair		
				(Refer labour no. 4 & 5)	
				\$ 3,710.40	\$ 2,469.40
Less Discount : 10%				\$ 371.04	\$ 246.94
List Parts Sub-Total :				\$ 3,339.36	\$ 2,222.46
1	1 set	Frt no.plate (w/bracket)	Dented/Cracked	\$ 50.00	\$ 50.00 40 ✓
Special Nett Sub-Total :				\$ 50.00	\$ 50.00
Parts Total :				\$ 3,389.36	\$ 2,272.46 ✓



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJN6670J

Report No. : PAS/TP/0190122

S/No. Labour Descriptions

Repairer's Our
Estimate (S\$) Assessment (S\$)

1	To remove and reinstall electrical wiring system for necessary repairs. To check electrical system, repair wire harness and focus headlamp.	\$ 50.00	\$ 30.00 ✓
2	To remove, reinstall radiator, a/c condenser and pipings for necessary repairs. (Include pressure test cooling system and vacuum, recharge a/c gas)	\$ 200.00	\$ 180.00 X
3	To transfer front bumper skirt to new bumper and supply sealant/adhesive tape.	\$ 60.00	\$ 60.00 30
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 700.00 400
5	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 750.00 600
Labour Total :		\$ 2,310.00	\$ 1,720.00

Total (Parts & Labour) :

\$ 5,699.36 \$ 3,992.46 ✓

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,190.00

Under normal circumstances, the repairs should be completed within a reasonable period of 6 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

40 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.