

Certification for Bus Repairs



CBR REF NO. : SE20223754

Depot : SE **Report No.:** AR-2022-1720 **BUS VEHICLE NO. :** SG5062B
Driver's Co no. & Name : 16027 Tong Mun Loo
Accident Date : 05/08/2022

Date in : 05/08/2022

Date Out : 23/08/2022

Yr Of Reg	Make / Model	Chassis No.
2016	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P923GA176864

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30541666	DIPPED BEAM HEADLAMP	1	\$68.00
30112002	FRT O/S LIGHT BEZEL COMP MOULD-CL 2;FRT	1	\$95.00
30750000	FRT OS CORNER DEFLECTOR COMP MOULD CL1	1	\$65.00
30112003	O/S CORNER BUMPER COMP MOULD-CL 1.FRT	1	\$230.00
30541665	MAIN BEAM HEADLAMP	1	\$58.00
99002077	SPRAY PAINT- GREEN;600ML;SG BUS	600	\$30.00
99002027	SPRAY PAINT - BLACK (PYLOX)	1	\$2.51

TOTAL FOR PARTS			S\$ 548.51
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	188.00
2	Contractor's repair charges	S\$	950.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 1138.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 1686.51

Certification for Bus Repairs



CBR REF NO. : SE20223754

Depot : SE Report No.: AR-2022-1720 BUS VEHICLE NO. : SG5062B
Driver's Co no. & Name : 16027 Tong Mun Loo
Accident Date : 05/08/2022

Date in : 05/08/2022

Date Out : 23/08/2022

Yr Of Reg	Make / Model	Chassis No.
2016	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P923GA176864
TOTAL DAMAGE		S\$ 1686.51
Overheads		S\$ 505.95
Towing Charges		S\$ -
Repair Period : 3 day(s)	Loss of Use	S\$ 1263.93
TOTAL LOSS		S\$ 3456.39

Prepared By : Nurizman Bin Yusoff

Date : 29/08/2022

Approved By
Workshop Mgr : Zee Chee Wah

Date : 30/08/2022

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 3456.39

Acknowledged By
Depot Safety : Tham Meng Khuan

Date : 30/08/2022

* This is computer generated document and does not require signature