

AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087

Tel: (65) 6253 0233 Email: sales@autoteam.com.sg

Co. Reg. No. 201205841K



INVOICE

Bill To

SBS Transit Ltd
Seletar Workshop
3 Yio Chu Kang Crescent
Singapore 786010
Attn: Finance Dept

Invoice No. IN22081041
Date 24 Aug 2022
P/O No. SBST0000135844
Terms Net 30

S/No	Description	ManHou	ManHour Rate	Amount
<u>Repair Accident Bus - SG 5062B</u>				
1.	Supply workers for 19 ManHours	19	S\$50.00	S\$950.00
-	Replace Right Side Headlamp			
-	Replace Right Side Headlamp Cover			
-	Replace Right Side Front Corner Bumper			
-	Replace Right Side Front Dome			
-	Repair Front Dome			
-	Repair Right Side Panel No. 1			
-	Repair Interior Front Dome			
-	Spray Painting Right Side Headlamp Cover			
-	Spray Painting Right Side Front Corner Bumper			
-	Spray Painting Right Side Front Dome			
-	Spray Painting Front Dome			
-	Spray Painting Right Side Panel No. 1			

827 ✓

GRSE - 22005094

Comments	Total	S\$950.00
----------	-------	-----------

All cheques should be crossed and made payable to
AUTOTEAM ENGINEERING PTE LTD

Issued By

