



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III22005648/Tvy3e2-1	
			Date: 05/12/2022	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 109D	Veh. Inspected	SKJ 5858B
	Policy No.	D19MFL0000003_03	Coverage (\$)	0.00
	Claim No.	MFL2022D0003119	Excess (\$)	0.00
	Assign From	CARINE KEK	Assign Date	08/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PREVIA	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTEGD54M80A016241	Colour	WHITE
	Odometer	191582 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	KENDA	6 mm
	L/H Front Tyre	215/55 R17	KENDA	6 mm
	R/H Rear Tyre	215/55 R17	KENDA	6 mm
	L/H Rear Tyre	215/55 R17	KENDA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/06/2022	Inspection Date	14/06/2022
	Survey held at	SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	