ALLIED AUTO APPRAISAL

22 Upper Serangoon Crescent #16-53 Singapore 534025

Company Registration No. 53127765B

Our Ref: SV/IND/B2-06005

Address of Inspection

8 Kaki Bukit Ave 4 #02-24 Premier Kaki Bukit Singapore 415875

. Owner Name

Nur Shuhada Binte Suhaimi

S V Autoworks Pte Ltd

Date of GIA Report Date of Accident

Date of Survey Date of Survey Report

Vehicle Number

11-Jun-22 11-Jun-22 17-Jun-22

SKJ 5858 B

8-Jul-22

VEHICLE PARTICULARS & CONDITION

Make & Model

Toyota Previa . 2AZH364876 :

Date of Registration Engine c.c.

24-Sep-09 2362 cc

Engine No Chassis No

Repairer

JTEGD54M80A016241

COE Expiry Date

31-May-29

CONDITION OF VEHICLE

General Condition Steering

Good Serviceable

Modification Air-Conditioner:

No Yes

Handbrake Wing Mirror Serviceable

Footbrake Paint Work Serviceable Good

CONDITION OF TYRES

Yes

(The below values represent the remaining tyre treads depth)

215/55R17 :

Rear Tyre Size :

215/55R17

Front Tyre Size Front Left Side

6mm Michellin

Rear Left Side 6mm Michellin

Front Right Side

6mm Michellin

Rear Right Side 6mm Michellin

GENERAL DESCRIPTION OF DAMAGE

The inspected vehicle sustained damage at the REAR RIGHT portion.

During visual inspection, our surveyor noted that the rear door right, rear fender right, rear bumper, taillamp right and among other parts were affected.


All stated damage is subject to consistency of the accident reports.

7,587.30

2,870.00

11,017.30

560.00



Repairer Estimate

Parts 2 Nett Item 2 Labour . Total

Our Recommendation

Parts:

7,587.30

Nett Item: Labour:

560.00 2,370.00

GST (7.00%):

Total:

10,517.30

Less 20%:

2,103.46

8,413.84

Lump Sum (Estimated):

8,400.00

The repairer agree to repair the vehicle on a Lump Sum Basis with our recommendation of SGD 8,400.00 (SGD Eight Thousand Four Hundred only) and we are in the opinion the repairer would need about a 8.0 working day period to repair the vehicle.

Allied Auto Appraisal

Surveyed by Ng Heng Chai Licensed Appraiser

ALLIED AUTO APPRAISAL

No.	No.	MMENDED PARTS Descriptions	Condition	Qty	Repairer	Adjusted	
3 REAR DOOR WINDOW MOTOR RH SHORTED 1 345.50 345.50 √ M 4 REAR DOOR LOCK RH JAMMED 1 335.10 335.10 √ M 5 REAR FENDER RH DENTED 1 1,045.50 1,045.50 6 REAR FENDER INNER COWLING RH CUT 1 284.60 284.60 // 0 7 REAR RENDER MID FAP CUT 1 212.60 212.60 7 REAR RENEREL HOUSING PANEL RH DENTED 1 1,335.80 1,335.80 √ M 9 REAR WHEEL HOUSING PANEL RH DENTED 1 1,335.80 1,335.80 √ M 9 REAR BUMPER RETAINER 1 CRACKED 1 1,091.50 1,091.50 € 7	1	REAR DOOR RH					
## REAR DOOR LOCK RH JAMMED 1 335.10 335.10 1 345.50 1 1 345.50 1 1 345.50 1 1 345.50 1 345.50 1 1 345.50 1 345.50 1 1 321.50 1 335.80 1 345.80 1 345.80 1 345.80 1 345.80 1 345.80 1 335.80 1 335.80 1 345.80 1 335.80 1 345.80 1 335.80 1 345.80 1 335.80 1 345.80 1 335.80 1 335.80 1 345.80 1 335.80 1 355.80 1 10.01.50 1 10.05.50 1 10.05.50 1 10.05.50 1 10.05 1 10	2			1		345.50 \(\lambda \times \text{1} \) 335.10 \(\lambda \text{1} \text{1} \text{1} \) 1,045.50 284.60 \(\lambda \text{1} \text{0} \text{0} \)	
S REAR FENDER RH	3	REAR DOOR WINDOW MOTOR RH					
REAR FENDER INNER COWLING RH CUT 1 284.60 284.60 10 10 10 10 10 10 10	4	REAR DOOR LOCK RH					
The standard of the standar	5			1			
REAR WHEEL HOUSING PANEL RH DENTED 1 1,335.80 1,335.80 1	6						
9 REAR BUMPER GRAZED 1 1,091.50 1,091.50 6	7						. #
10 REAR BUMPER RETAINER 1 CRACKED 1 112.50 112.50 112.50 112 FAREA BUMPER RETAINER 2 CRACKED 1 108.50 108.						1,335.80 K	γ - < - < - - < - - <
11 REAR BUMPER RETAINER 2	9	REAR BUMPER	GRAZED	1			57601
12 TAILLAMP RH	10	REAR BUMPER RETAINER 1	CRACKED	1			
AIR CON BLOWER	11	REAR BUMPER RETAINER 2	CRACKED	1			
Sub Total (S\$): 10,116.40 10,116.40 2,529.10	12	TAILLAMP RH	GRAZED	1			28.10
No. Descriptions Condition Repairer Adjusted	13	AIR CON BLOWER	CRACKED	1 _			÷1277 := "
No. Descriptions Condition Repairer Adjusted			Sub Total (S\$)	\$.	3		5027.0.
No. Descriptions Condition Repairer Adjusted			Discount (25%)	·	2,529.10	10,116.40 5027.0 2,529.10 3770.3	
No. Descriptions Condition Repairer Adjusted			Total Parts (S\$)		7,587.30	7,587.30	7110.7
REAR DOOR RH INNER TRIM CLIPS NECESSARY 1 100.00	ECOM	MENDED SPECIAL NETT ITEMS					
2 REAR FENDER RH SEALANT NECESSARY 1 120.00 120.00 € 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	No.	Descriptions	Condition		Repairer	<u>Adjusted</u>	•
3 REAR WHEEL HOUSING RH SEALANT NECESSARY 1 120.00 120.00 € 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1	REAR DOOR RH INNER TRIM CLIPS	NECESSARY	1	100.00	100.00	(nn
4 REAR FENDER RH QUARTER GLASS SEALANT NECESSARY 1 120.00 120.00 60 000 150.00	2	REAR FENDER RH SEALANT	NECESSARY	1	120.00	120.00 (50vec/
TOTAL PARTS	3	REAR WHEEL HOUSING RH SEALANT	NECESSARY	1	120.00	120.00 X	[ww
TOTAL PARTS	4	REAR FENDER RH QUARTER GLASS SEALANT	NECESSARY	1	120.00	120.00 (50 ver/
Section Sec	5	REAR BUMPER CLIPS	NECESSARY	1			
Repairer Adjusted 1				· ·	560.00		150
1 PANEL BEATING THE AFFECTED PARTS. REMOVE, REFIX AND REPAIR THE AFFECTED PORTIONS. 2 TO CHECK WIRING. 3 TO WATER TESTING. 4 TO REMOVE & REFIX REAR FENDER QUARTER GLASS. 5 TO SPRAY PAINTING AT AFFECTED PORTIONS. 1,000.00 1,000.00 € € € € € € € € € € € € € € € € €	сом	MENDED LABOUR					
THE AFFECTED PORTIONS. 2 TO CHECK WIRING. 3 TO WATER TESTING. 4 TO REMOVE & REFIX REAR FENDER QUARTER GLASS. 5 TO SPRAY PAINTING AT AFFECTED PORTIONS. 5 TO SPRAY PAINTING AT AFFECTED PORTIONS. 5 TO	No.				Repairer		
THE AFFECTED PORTIONS. 2 TO CHECK WIRING. 3 TO WATER TESTING. 4 TO REMOVE & REFIX REAR FENDER QUARTER GLASS. 5 TO SPRAY PAINTING AT AFFECTED PORTIONS. 5 TO SPRAY PAINTING AT AFFECTED PORTIONS. 5 TO TO LAIMS Repairer Adjusted 7,587.30 7,	1	PANEL BEATING THE AFFECTED PARTS. REMOVE,	REFIX AND REPAIR		1,500.00	1,000.00	700
3 TO WATER TESTING. 100.00 100.00 共の 4 TO REMOVE & REFIX REAR FENDER QUARTER GLASS. 150.00 150.00 8 0 150.00 8 0 150.00 8 0 150.00 8 0 150.0		THE AFFECTED PORTIONS.					
4 TO REMOVE & REFIX REAR FENDER QUARTER GLASS. 150.00 150.00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2	TO CHECK WIRING.			120.00	120.00	40
4 TO REMOVE & REFIX REAR FENDER QUARTER GLASS. 150.00 150.00 ₹ 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3	TO WATER TESTING.			100.00	100.00	40
5 TO SPRAY PAINTING AT AFFECTED PORTIONS. 1,000.00 1,000.00 2,370.00 ST OF CLAIMS Repairer Adjusted 1 TOTAL PARTS 7,587.30 7,587.30 2 TOTAL NETT ITEMS 560.00 560.00 3 LABOUR & SPRAY 2,870.00 2,370.00 Gross Total (\$\$): 11,017.30 10,517.30							
2,870.00 2,370.00 ST OF CLAIMS Repairer Adjusted 1 TOTAL PARTS 7,587.30 7,587.30 2 TOTAL NETT ITEMS 560.00 560.00 3 LABOUR & SPRAY 2,870.00 2,370.00 Gross Total (\$\$): 11,017.30 10,517.30							
ST OF CLAIMS Repairer Adjusted 1 TOTAL PARTS 7,587.30 7,587.30 2 TOTAL NETT ITEMS 560.00 560.00 3 LABOUR & SPRAY 2,870.00 2,370.00 Gross Total (\$\$): 11,017.30 10,517.30	_					2,370.00	1660
1 TOTAL PARTS 7,587.30 7,587.30 2 TOTAL NETT ITEMS 560.00 560.00 3 LABOUR & SPRAY 2,870.00 2,370.00 Gross Total (\$\$): 11,017.30 10,517.30	ST OF	CLAIMS					
2 TOTAL NETT ITEMS 3 LABOUR & SPRAY 560.00 2,870.00 2,370.00 Gross Total (\$\$): 11,017.30 10,517.30				يستونين			•
3 LABOUR & SPRAY 2,870.00 2,370.00 Gross Total (\$\$): 11,017.30 10,517.30							
Gross Total (S\$) 11,017.30 10,517.30							
		EDDOUG STINI	Gross Total (SC)	١,٠			•
CCT 7 00% (CC) •			GST 7.00% (S\$)		11,017,50	10,517.50	
Total Amount (S\$): 11,017.30 10,517.30					** 047.00	40.545.55	-

3770.30 150 1660 5580.30 11594450 27deys *