

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120
T : (65) 6419 3000
www.aig.sg

Claim No: 0161496872SG **Date of Survey:** 21/12/2021
Repairer: TRANS EUROKARS PTE LTD - TANJONG PENJURU

REFERENCE

Insured: ALEXIUS CHEW HUI JUN **Policy No:** 2070171356
Date of Loss: 18/12/2021 **Nature of Claim:** OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SMX6065T
Make & Model: MAZDA 2, 1.5 HATCHBACK STANDARD I4 (A) **Reg. Date:** 21/01/2021
Engine No: P520719247 **Chassis No:** JM6DJ2HAA01400113

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes
		Pre-accident Condition:	Good

TOTAL OFFER

Offer Authorized By:	NG, THADDAEUS-HC on 03 Mar 2022 15:25
Offer Initiated By:	NG, THADDAEUS-HC on 21 Dec 2021 16:17
Subrogation:	Yes
Rep. Gross Total:	S\$10,311.84 [Diff: S\$4,734.52, 45.91%]
Approved Gross Total:	S\$5,577.32
- Excess:	S\$0.00 [Waived: S\$600.00] [Remarks: Not Applicable]
	S\$5,577.32
+ GST (7.00%):	S\$390.41
Approved Nett Amount:	S\$5,967.73 (No Betterment/Depreciation)

Special Remarks: Damaged parts as require only approval with acknowledgement during physical repair for your attention. Kindly do not hesitate to update resurvey for check and supplementary item

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	2,731.84	1,702.32	1,029.52	37.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	3,875.00	3,705.00	48.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$)	10,311.84	5,577.32	4,734.52	45.91
+ GST 7.00/7.00% (\$)	721.83	390.41	331.42	45.91

Nett Amount (S\$)

11,033.67

5,967.73

5,065.94

45.91

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 5.0 days

Authorised Repair : Yes

Inspection conducted by : Ng, Thaddaeus-HC (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	BR	893.40 FL	*893.40 FL	✓
2	1		*BRACKET CENTER REAR BUMPER		5.40 FL	Serviceable	NN X
3	2		*STAY REAR BUMPER		47.60 FL	Serviceable	X NN
4	1		*RETAINER LH REAR	BR	27.20 FL	*27.20 FL	✓
5	1		*SPLASH SHIELD LH REAR	TN	52.10 FL	*52.10 FL	✓
6	1		*FINISHER REAR LH		27.50 FL	Serviceable	X NN
7	4		*GROMMET,SCREW	NEC	10.80 FL	*10.80 FL	✓
8	1		*BRACKET REAR BUMPER	NEC	26.00 FL	*26.00 FL	✓
9	7		*FASTENER	NEC	21.00 FL	*21.00 FL	✓
10	1		*TAIL LAMP LH	BR	683.00 FL	*683.00 FL	✓
11	1		*FASTENER,LAMP		15.70 FL	Reuse	X NN
12	1		*REAR END PANEL		477.10 FL	Repair	X R
13	1		*REAR FENDER LOWER N0.2	BT	183.60 FL	*183.60 FL	✓
14	1		*REAR FENDER LOWER N0.1		216.90 FL	Repair	X R
15	1		*CHAMBER,EXTRACTOR	BR	49.20 FL	*49.20 FL	✓
16	1		*BODY SIDE MIRROR LH		372.80 FL	Serviceable	X NN
17	1		*LAMP SIGNAL TURN LH		123.90 FL	Serviceable	X NN
18	1		*COVER SIDE MIRROR LH	MIS	128.40 FL	*128.40 FL	✓
19	1		*GLASS&HOLDER LH,MIRROR	BR	53.20 FL	*53.20 FL	✓

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,414.80	2,127.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	682.96	425.58
Total Parts (\$\$)	2,731.84	1,702.32

AIG Asia Pacific Insurance Pte. Ltd./SMX6065T/03/03/2022 15:25

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR END PANEL , REAR FENDER LOWER LH AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS. 660 day	New	2,520.00	945.00 ✓
2	TO RESPRAY REAR BUMPER, REAR END PANEL, REAR FENDER LOWER LH, REAR FENDER LH, REAR DOOR LH, FRONT DOOR LH AND ALL AREAS AFFECTED BY THE ACCIDENTS. 630 panel	New	4,200.00	2,400.00 ✓
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING Not Require	New	180.00	0.00 ✗
4	TO TRANSFER REVERSE SENSORS .	New	180.00	180.00 ✓
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	200.00	150.00 ✓
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	250.00	180.00 ✓
7	SUNDRIES.	New	50.00	20.00 ✓
Gross Labour Cost (\$\$)			7,580.00	3,875.00

AIG Asia Pacific Insurance Pte. Ltd./SMX6065T/03/03/2022 15:25

< END OF REPORT >

Part by part

5 days