

STG 588R 2008 June

T? Chim.

Hand Fit 1339 cc

Veron.

GE61080973

Rear Number Plate	Bent	30(SN)	✓
Rear Number	Holder behind	30(SN)	✓
Rear Bumper	Distorted	\$55.40	✓
Rear Bumper Clips	new	30(SN)	✓
Rear Bumper Side Holder x 2	end	$24.9 \times 2 = 49.80$	✓
Rear Bumper Tow Cover.	Distorted	30.40	✓
Reverse Sensor	Damaged	282(SN) 200(SN)	✓
Rear End Panel	Distorted	468.50	✓
Rear End Panel Top Garnish	behind	155.60	✓
Rear End Panel Top Garnish	Clips new	20(SN)	✓
Rear End Panel Sealant	new	60(SN)	✓
Taillamp x 02	LH at RH cracked	$286.4 \times 2 = 572.80$	✓
Taillamp Panel x 02	RH Dented	$225.8 \times 2 = 451.60$ 225.80	✓
Tailgate	Distorted	859.60	✓
Tailgate lock	new	193.50	✓
Tailgate weatherstripe.	at	161.50	✓

SIG 688R.

Tailgate Outer Garnish	new	159.50	✓
Clips.	new	30(SN)	✓
Tailgate Inner Trim Board.	Debond	285.80	✓
Tailgate Glass Moulding	new	124.10	✓
Tailgate Glass Sealant.		60(SN)	✓
Rear RH Fender.	Buckled	820.40.	✓
Rear RH Fender Glass Moulding	new	65.10.	✓
Rear RH Fender Glass Sealant.		40(SN)	✓
Rear Fender Inner Trim Board	802 Debond	295.9 x 2 = 591.80	✓
Rear Fender Inner Trim Board Clips.	new	60(SN)	✓
Spare Tyre Panel	Buckled	737	✓
Spare Tyre Panel Top Board.	Debond	183.90	✓
Tools Tray sponge.	Deformed	265.90	✓
Rear Exhaust Pipe	Bent	586.40	✓
Rear Exhaust Moulding	new	39.40	X
Rear Exhaust Heat Shield	crushed	120.40	✓
Rear Exhaust Gasket.	new	35.20	✓
Rear Axle	the new	1206.80	X

SJR 588R.

Rear Wheel Hub c/w Bearing x02 } $255.3 \times 2 = 510.60$
X4
Rear 240.4 x 2 = 480.80. X

Rear Shock Absorber x02.

Honda Logo BSR R

Fit Emblem R

35.90 X

40.80 ✓

~~1800~~ 1600
~~1800~~ 1100

Panel Bery

Spring Faulty

~~100~~ 30

wiring.

~~100~~ 50

To remove case sensor.

~~200~~ 100

To apply tuff coat

~~150~~ 80

To remove upholstery,

~~150~~ 80

To transfer tailgate fittings

~~180~~ 120

To remove tailgate glass

~~120~~ 50

To remove rear bumper glass

~~150~~ 80

To remove exhaust pipe.

450 X

To remove rear undercarriage.

150. X

To perform wheel alignment.

15,558.90

SGG 588R.

hist: 7070.10

Labour: 3290

Less 20%: 5656.08

total: 9476.08

S.N: 530

H/S: 7.51C.

12 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: