



SINGAPORE POLICE FORCE



T/20171130/2117

Page 1 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20171130/2117

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/11/2017 17:14		Vide Report No.:		Station Diary No.: 60	
Informant's Particulars					
Name of Informant: CHIEW LI LI			Address: 36 JALAN GAHARU SINGAPORE 588859		
ID Type / ID No.: NRIC NO / S7127891C			Contact No.: Home/Office:		Mobile: 92744373
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 46	Date of Birth: 08/08/1971	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: Other business services and administration managers nec			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 30/11/2017 14:40	Type of Location: Straight Road
Location: Along Road 1 UBI AVENUE 1				
At 53 ubi ave 1 #01-03				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBC507R	Motorcycle					0
FBJ54T	Motorcycle					0
FBK6324U	Motorcycle					0
FBL3086X	Motorcycle					0
PGT7199	Lorry					0



**SINGAPORE
POLICE FORCE**



T/20171130/2117

3 of 3

Police Station Of Origin:

Geylang N.P.C

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

Report No. T/20171130/2117

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 LING JUNXIAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Signature Of Informant:

Date/Time:

30/11/2017 17:14

Classification Of Case:

Authentication Stamp

NP168

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company 200918802W
Cert No.:
Owner ID Type: Company
Owner Name: GLOBAL MOTOR PTE. LTD.
Registered Address: 53 UBI AVENUE 1 #01-12 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: FBM4980C
Previous Vehicle No.: FBJ54T
Effective Date of Ownership: 31 Jul 2017
Original Regn Date: 31 Jul 2017
Registration Date: 31 Jul 2017
Year of Manufacture: 2017
Vehicle Type: Passenger Scooter
Vehicle Scheme: -
Vehicle Attachment 1: No Attachment
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: KYMCO
Vehicle Model: AK550
Primary Colour: Silver

Secondary Colour: -

Passenger Capacity: 1
Chassis No.: RFBE10000H1600113
Engine No.: SAA11600115
Engine Capacity/Power Rating: 550 cc / -
Maximum Power Output: -
Propellant: Petrol
Max Unladen Weight: 230 kg
Maximum Laden Weight: 395 kg
Open Market Value: \$7,812.00

GLOBAL MOTORSPORT

53 Ubi Ave 1 #01-12 Paya Ubi Industrial Park, Singapore 408934

Tel : 63453687 Fax : 67485449

Company Registration No: 53143853L

INVOICE

To: Global Motor Pte Ltd
53 Ubi Ave 1 #01-12
Paya Ubi Ind Park, S408934

Invoice No.: GM0218/086

Date : 7 Feb 2018

Vehicle No.: FBM4980C

**RE: ACCIDENT INVOLVING FBM4980C AND PGT7199 ON 30 NOVEMBER
2017 AT 1440 HOURS ALONG ROAD 1 UBI AVE 1**

DESCRIPTION

AMOUNT

Lump Sum Repair
Documentation Fee

\$7,700.00


\$ 250.00

\$7,950.00

=====

Singapore Dollars: Seven Thousand Nine Hundred and Fifty Only.

For and on behalf of
Global Motorsport





INVOICE

TO : GLOBAL MOTORSPORT
C/O: GLOBAL MOTORSPORT
53 UBI AVE 1 #01-12 PAYA UBI IND
PARK
SINGAPORE 408934

Invoice No.: 1217/GM432
Date: 30 JANUARY 2018

PARTICULARS

Vehicle Registration No.: FBM 4980 C - AK550
Date of Loss: 30 NOVEMBER 2017
Date of Assessment: 06 DECEMBER 2017

SERVICES

FEES

1. Assessment with report Photographs - Including films, developing, storage and Transport.

\$350.00

TOTAL \$350.00

SINGAPORE DOLLARS THREE HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of
the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: GLOBAL MOTORSPORT
C/O: GLOBAL MOTORSPORT
53 UBI AVE 1 #01-12 PAYA UBI IND PARK
SINGAPORE 408934

Our Reference: 1217/GM432
Date: 30 JANUARY 2018

ASSESSMENT OF VEHICLE NO. FBM 4980 C DATE OF LOSS: 30/11/2017

We have carried out a physical assessment of FBM4980C at **GLOBAL MOTORSPORT**, 53 Ubi Ave 1 #01-12 Paya Ubi Ind Park, Singapore 408934, according to your instruction on **06 DECEMBER 2017** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: FBM 4980 C
Make & Model: KYMCO AK550
Year of Registration: 2017

Colour: SILVER
Mileage: 000000

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front

Make/Size/Thread: METZELER 120/70 15R - 100%

Rear

Make/Size/Thread: METZELER 160/60 15R - 100%


4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the RHS and LHS portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na

Estimated Amount:	\$ 8,078.00
Adjusted Amount:	\$ 7,708.00 (Lump Sum of \$7,700.00)
Estimated Repair Days:	8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a **"Without Prejudice"** basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. FBM 4980 C - AK550

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	WIND SHIELD	Cracked	273.00	273.00
1	HANDLE BAR	Bent	148.00	148.00
1	HANDLE BAR TOP COVER	Cracked	24.00	24.00
1	HANDLE BAR BOTTOM COVER	Cracked	24.00	24.00
1	RH THROTTLE GRIP	Cut	90.00	90.00
1	RH BRAKE LEVER	Bent	234.00	234.00
1	HEADLAMP COMPLETE LED	Cracked	1,284.00	1,284.00
1	HEADLAMP GRILL (METALLIC CHROME)	Cracked	215.00	215.00
1	RH FRONT FORK COMPLETE	Bent	719.00	719.00
1	FRONT FORK RH COVER	Cut	31.00	31.00
1	FRONT RIM	Cut	953.00	953.00
1	RH FRONT COVER	Cracked	165.00	165.00
1	RH CENTRE COVER	Cracked	88.00	88.00
1	RH SIDE SKIRT	Cracked	112.00	112.00
1	RH PILLION FOOTREST	Cut	25.00	25.00
1	MUFFLER COMPLETE	Bent	1,735.00	1,735.00
1	MUFFLER COVER	Bent	112.00	112.00
1	RH FRONT WINKER LAMP LED	Cracked	173.00	173.00
1	LH FRONT WINKER LAMP LED	Cracked	173.00	173.00
			6,578.00	6,578.00
Less 0% discount			0.00	0.00
Parts Total:			6,578.00	6,578.00

ASSESSMENT REPORT FOR VEHICLE NO. FBM 4980 C – AK550

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	Spray painting	500.00	330.00
2	Labour for repair and replace parts.	1,000.00	800.00
Labour Total :		1,500.00	1,130.00
TOTAL (PARTS & LABOUR) \$		8,078.00	7,708.00

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is **\$7,700.00** (SINGAPORE DOLLARS SEVEN THOUSAND SEVEN HUNDRED ONLY)



Amas Ong
Automobile Assessor

















