

ASS. REC. BY:

REF:

AIC.
A15/22 011321/kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + RS SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Authorized
 6/1 Rm @
 Pending After Paint
 5 days

LM AUTO SOLUTION PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C,

#01-12 Singapore 575645

Email: admin@lmautosolution.com

Tel: 90162222

VEHICLE NUM:

SLV 6236 P

MAKE & MODEL:

MERC C180

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	HEADLAMP ASSY RH <i>mg cm ✓</i>	1	
2	HEADLAMP BRACKET RH <i>?</i>	1	
3	FRONT BUMPER <i>mg cm ✓</i>	1	
4	FRONT BUMPER RETAINER RH <i>D.O ✓</i>	1	
5	FRONT BUMPER SENSOR RH <i>?</i>	2	
6	FRONT BUMPER GRILLE RH <i>in x</i>	1	
7	FRONT BUMPER INNER BRACKET <i>rx</i>	1	
8	FRONT BUMPER SPONGE <i>?</i>	1	
9	FRONT BUMPER REINFORCEMENT <i>rx</i>	1	
10	FRONT BUMPER CLIP [SET] <i>new</i>	1	
11	FRONT GRILLE ASSY <i>in x</i>	1	
12	FRONT FENDER RH <i>new</i>	1	
13	FRONT FENDER COWLING RH <i>D.O ✓</i>	1	
14	FRONT FENDER COWLING CLIP RH [SET] <i>new</i>	1	
15	FRONT SUPPORT PANEL ASSY <i>rx</i>	1	
16	FRONT ABSORBER RH <i>?</i>	1	
17	FRONT KNUCKLE RH <i>?</i>	1	
18	FRONT KNUCKLE BEARING RH <i>?</i>	1	
19	FRONT LOWER ARM RH <i>?</i>	1	
20	FRONT UPPER ARM RH <i>in x</i>	1	
21	FRONT TRAILING ARM RH <i>?</i>	1	
22	FRONT TRUST ARM RH <i>in x</i>	1	
SUBTOTAL			\$ -
5%			\$ -
PARTS TOTAL			\$ -

SPECIAL NETT

		QTY	PRICE	
1	FRONT RIM RH <i>P, ?</i>	<i>Red</i> 1	\$ 2,200.00	✓
2	FRONT TYRE RH	<i>in</i> 1	\$ 600.00	X

SPECIAL NETT \$ 2,800.00

LABOUR

		QTY	PRICE	
1	TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$ 800.00	<i>500/</i>

