

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

or _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date/Time

Action/Instructions

MV-162K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.H. (%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Responsibility

S.S. + P.S. (\$)

Notes

Others

TOTAL

Veh No:

YA 5893X

Yr Regn:

24/3/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Private Motor

Truck / Trailer or

Make:

Hino FG8JR1A

7685

Colour:

White

A/C: Insured / Std / N/A

Sp. Reading

70652

T/Radio: Insured / Std / N/A

Eng/No:

C/No:

JEDF6 85R 7 XXX 10050

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

275/80R225

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / A/C / ORT / PIR / SUM /

TOYO / YOKO or .

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

U/Bal.

5

mm

U/Bal.

5

mm

D.O.A.

27/11/22

D.O.I.

14/11/22

Survey held at

Big fort

Des. of Damages: Frt / Rear / O/S / N/S / U / Roof top or

The UIC / Chassis frame / Body Structure affected due to collision.

REPAIR INITIAL QUOTATION FOR PRS
BIG-FOOT ENGINEERING PTE LTD

Date: 14/11/2022

Vehicle Number: YQ5893X

Make & Model: HINO

3rd party vehicle YP9501G

DOA / Location: 55 UBI AVE 1

3rd Party Vehicle / Insurance: Allianz Insurance Singapore

Qty	Description / Part	Unit Price	Total
1	To replace side mirror / <i>OR</i>	\$ 220.00	\$ 220.00 ✓
2	To repair RH freezer box / <i>OR</i>	\$ 3,200.00	\$ <i>2500</i> 3,200.00
3	To reinstate advertisement / logo sticker / <i>rec</i>	\$ 1,200.00	\$ <i>1000</i> 1,200.00
4	Labour to remove, refix parts, putty & respray	\$ 3,200.00	\$ <i>2500</i> 3,200.00
			\$ 7,820.00
		Less 10%	\$ 782.00
		Sub Total	\$ 8,602.00
		7% Gst	\$ 602.14
		G/Total	\$ 9,986.14
5	Loss Of Use (LOU) - <i>5</i> days @ \$250.00 per day	\$ 250.00	\$ 1,750.00
		Grand Total	\$ 11,736.14

The results of the checks are valid at the time of inspection. Quotation will be subjected to changes upon further rectification / inspection.

Steve CLKKJ 8322 8813
14/11/22, 3:30pm
[Signature]

Surveyor Name & Signature

PJP
[Signature]

Date & Time of Surveyed

** Do not spray, Surveyor will take photo first*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____