

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0992/2022/EQ  
**DATE** : 11-Nov-22  
**WIP** : 49841

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/11/2022**

**YOUR INSURED VEH NO : SND 1507 L**

**China Taiping Insurance (S) Pte Ltd**

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

**OWNER'S NAME** : MR NG THIAM SIONG  
**ADDRESS** : 28 TOMLINSON ROAD  
#13-30  
SINGAPORE 247854  
**TELEPHONE** : HP +65 82228212  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : PNPV2021-00002069-01  
**VEHICLE NO** : **SJB 323 P**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 30/4/2021  
**ENGINE NO** : DEM 031679  
**CHASSIS NO** : WAUZZZF55MA039717  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Nov-22  
**PLACE OF ACCIDENT** : PIE TOWARDS UBI NEAR KALLANG  
EXIT SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 323 P**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N \$	400.00	
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	
6	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 10,660.00</b>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 323 P**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL AND REAR END PANELLING.	\$ 5,500.00	
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 16,632.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,609.00	
2	REAR BUMPER SECURING STRIP	1	\$ 125.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER SPOILER	1	\$ 276.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 96.00	
6	REAR OUTER TAIL LIGHT - RH	1	\$ 1,269.00	
7	REAR BUMPER GUIDE SECTION - RH UPPER	1	\$ 26.00	
8	REAR BUMPER GUIDE SECTION - RH	1	\$ 49.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
10	REAR PARKING AID SEAL RING	4	\$ 10.00	
11	REAR SIDE PANEL - RH	1	\$ 4,076.00	
12	REAR QUARTER WINDOW - RH	1	\$ 798.00	
13	REAR FUEL INSERT	1	\$ 100.00	
14	REAR WHEEL HOUSING LINER - RH	1	\$ 299.00	
15	ATTACHMENT PARTS	1	\$ 136.00	
16	ADHESIVE TAPES	1	\$ 221.00	
17	REAR VENT TRIM	1	\$ 75.00	
18	REAR ALUMINIUM RIM	1	\$ 1,889.00	
19	REAR ALUMINIUM RIM VALVE	1	\$ 4.00	
20	REAR PARKING AID SENSOR	1	\$ 266.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 13,104.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 323 P**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	1/4 GLASS SEALANT	S/N	\$ 100.00	
22	ACRYLIC SEALANT	S/N	\$ 180.00	
23	CAVITY WAX	S/N	\$ 140.00	
24	STONE CHIP	S/N	\$ 180.00	
25	METAL FILLER POWDER	S/N	\$ 280.00	
26	SUNDRIES		\$ 500.00	
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 14,484.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 16,632.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 31,116.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT