

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011328/GVP3Q2**Date:** 06/01/2023**REFERENCE**

Insured/Claimant: YANG KUN Policy No: DMPCSNW00098442200
Date of Loss: 07/11/2022 Nature of Claim: OD Claim No: SNM22D208047/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ1870U**
Make & Model: MAZDA 6, 2.0 SEDAN EXECUTIVE EU6 (A) Engine No: PE21096659
Reg. Date: 25/04/2018 (Man. Year: 2018) Chassis No: JM6GL1071J0146059
Colour: White Odometer: 71484 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,540.00	3,256.00	2,284.00	41.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	508.20	373.80	134.40	26.45
Paintwork Labour	694.29	742.57	-48.28	-6.95
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,742.49	4,372.37	2,370.12	35.15
- Excess (S\$)	750.00	250.00	500.00	66.67
(S\$)	5,992.49	4,122.37	1,870.12	31.21
+ GST 7.00/7.00% (S\$)	419.47	288.57	130.90	31.21
Nett Amount (S\$)	6,411.96	4,410.94	2,001.02	31.21

INSPECTION

Date of Assignment: 11/11/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected: 11/11/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
6 Marsiling Lane
Singapore 739145
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ1870U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		4,990.00 F	*2,706.00 F
Supplementary #1						
2	1		*FRONT GRILLE CHROME RH	Cut	90.00 F	*90.00 F
3	1		*SUPPORT PANEL	Broken	265.00 F	*265.00 F
4	1		*SUPPORT SIDE PANEL	Bent	105.00 F	*105.00 F
5	1		*SUPPORT TOP PANEL	Bent	90.00 F	*90.00 F
F=Franchise part.						
Total Parts (S\$)					5,540.00	3,256.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	694.29	742.57
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	508.20	373.80
Gross Labour Cost (S\$)			1,202.49	1,116.37

Report was unsubmitted during this print-out.

< END OF ESTIMATES >