



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/12/2022

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5700T
Case Reference Number	BUS/11/22/5006
Registration Date	10/8/2017
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Xie Bangchun
Type of Accident	Head To Side
Accident Date and Time	4/11/2022 6:00 PM
Accident Reported Date and Time	9/11/2022 2:25 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116851
Special Instruction to ARC,if any	SG5700T - Left front bumper scratched. SMP512B (TP) - INSURED WITH INCOME
Prepared Date and Time	11/11/2022 10:41 AM
Chassis Number	SFD76CLR5GMTL4365
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,227.00	\$792.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	GuoQiang
ARC / Surveyor Sign Off Date	11/11/2022 10:44 AM	11/11/2022 2:13 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/12/2022

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$795.00				\$530.00	
Total Labour				\$795.00				\$530.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$432.00				\$262.00	
Total Spray Painting & Panel Beating				\$432.00				\$262.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011051	BODY LH	20594483/2	BUMPER,CORNER:L/H,F OR ADL E500 DD BUS	1.00	\$1,190.20	100.00	\$0.00	Repair	Repair
Total					\$1,190.20		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									