



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6509C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	BUCKLED/ MTG CRACKED	639.00	639.00
1	REAR BUMPER REINFORCEMENT	CRACKED	313.00	313.00
2	REAR BUMPER RETAINER @\$25.00	SERVICEABLE	50.00	-
10	REAR BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	REAR END PANEL	BENT	274.00	274.00
1	REAR END PANEL GARNISH	CRACKED	58.00	58.00
1	FRONT BUMPER	MTG CRACKED	639.00	639.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	496.00	-
1	FRONT BUMPER RETAINER	SERVICEABLE	50.00	-
10	FRONT BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	FRONT GRILLE	CRACKED	328.00	328.00
2	HEAD LAMP @\$2,209.00	N/S CUT	4,418.00	2,209.00
1	REAR BOOT LOCK (ADDITIONAL)	TO REPAIR SEE LABOUR	101.00	-
	LESS 10% DISCOUNT		-742.60	-452.00
			6,683.40	4,068.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER SENSOR (SN)	SERVICEABLE	200.00	-
1	FRONT NO PLATE (SN)	MISSING	40.00	40.00
1	REAR BUMPER SPOILER (ADDITIONAL) (SN)	CRACKED	680.00	680.00
			920.00	720.00
<b><u>LABOUR</u></b>				
	TO PUTTY & SPRAY PAINT.		1,200.00	800.00
	PAINT TREATMENT.		600.00	300.00
	TO CHECK FRONT WIRING & FOCUS HEAD LIGHTS.		35.00	30.00
	TO ANTI RUST.	NOT NECESSARY	80.00	-
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND REAR BOOT LOCK.		800.00	600.00

Report Ref No. CS/SMO22011332/Kvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINT PROTECTION FILM (ADDITIONAL).		150.00	150.00
			2,865.00	1,880.00
GRAND TOTAL			10,468.40	6,668.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CS/SMO22011332/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.