

FASTTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 20006262D

MS. No 709

not Audited
11/11/22
P/P 4524.92
3 days

VEHICLE No: PD 546G

1PC	FRONT BUMPER	DD	788.10	\$965.10	/
1PC	FRONT BUMPER SIDE HOLDER N/S	one	162.50	\$166.50	/
1SET	FRONT BUMPER CLIPS	per		\$50.00	/
1PC	FRONT BUMPER BEAM	Buf	615.30	\$655.20	/
1PC	FRONT BUMPER BEAM BRACKET N/S	R		\$258.50	X
1PC	FRONT BUMPER TOP BEAM	11		\$325.10	X
1PC	FRONT BUMPER FOG LAMP COVER N/S	twl		\$145.20	/
1PC	HEADLAMP N/S	one	1201.10	\$1,375.20	/
1PC	FRONT GRILLE OUTER CHROME ASSY	one	650.00	\$1,280.00	/
1PC	FRONT GRILLE INNER	one	645.20	\$785.10	/
1PC	FRONT CENTRE LOWER GARNISH	Torn	282.50	\$322.50	/
1PC	FRONT DOOR N/S	n		\$1,788.20	X
1PC	FRONT DOOR HINGE LOWER N/S	11		\$95.00	X
1PC	FRONT DOOR INNER RUBBER N/S	11		\$288.20	X
1PC	FRONT DOOR INNER TRIM BOARD N/S	11		\$651.20	X
1PC	FRONT DOOR OUTER HANDLE N/S	11		\$166.80	X
1PC	FRONT DOOR OUTER PILLAR N/S	R		\$1,099.20	X
1PC	FRONT STEP GARNISH N/S	11		\$341.50	X
1PC	FRONT STEP PANEL N/S	11		\$488.90	X
1PC	FRONT WIRE HARNESS N/S	11		\$650.50	X
1PC	FRONT WIRE HARNESS BRACKET N/S	11		\$255.20	X
1PC	FRONT CORNER PANEL N/S	11		\$466.10	X
1SET	FRONT DOOR 'ROC' STICKER N/S	11		\$50.00	X
1PC	FRONT DOOR VISOR N/S	11		\$80.00	X
				\$12,494.00	

252

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO TRANSFER FRONT DOOR MECHANISM
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
11 \$100.00 X
11 \$100.00 X
11 \$180.00 X
11 \$100.00 X
\$1,280.00 500
\$1,500.00 600
TOTAL \$15,804.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-4539-9
252
3404.92
1120
4524.92