



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Ref: CS3/ASM22011337/Gnp3

Date: 11/11/2022

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 7388A	Veh. Inspected	FBD 3551L
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04EB0	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	11/11/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/11/2022	Inspection Date	11/11/2022
Survey held at	KENG HOCK MOTOR 188 YIO CHU KANG ROAD, SINGAPORE 545635		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--