



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

21/12/2022

### Survey Details:

Date of loss	5-Nov-22
Date of appointment	11-Nov-22
Date of survey	11-Nov-22
Location of survey	KENG HOCK MOTOR

### Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	FBD 3551L
Make and Model	YAMAHA T135
Date of registration	
Excess	
Market Value	
Part Rebate	
Nett Loss	

### Repair details:

Initial Estimate	\$ -
------------------	------

### Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
<b>Total</b>	\$ -
<b>Lump Sum(if applicable)</b>	

<b>Number of days for repair</b>	<u>2</u>
----------------------------------	----------



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*No GIA Report provided. The estimate repair cost of the damaged vehicle is in the region of \$2,000.00 - \$3,000.00.*

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
<b>Proposed Total</b>	<b>#VALUE!</b>	