



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011341/Gny3m4 Date: 25/05/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5785E	Veh. Inspected	SNG 2991Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/22/2100	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	11/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI TL TUCSON FL 1.6	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHJ3812VKU964398	Colour	WHITE
	Odometer	51058 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60R17	MICHELIN	6 mm
	L/H Front Tyre	225/60R17	MICHELIN	6 mm
	R/H Rear Tyre	225/60R17	MICHELIN	6 mm
	L/H Rear Tyre	225/60R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2022	Inspection Date	11/11/2022
	Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	