

ASS. REC. BY:

REF: F62/22011344/kv

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: £34K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 789CYr Regn: 06.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NIS NV200C.C. 1961Colour: White / Green

A/C: Insured / Std / NI / NA

Sp. Reading: 188169

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM 207 0125389Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: Cam Forer 175/70R14R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 8 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 8/11/22D.O.I. 14/11/2022

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Rec estimate omitted.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

S - RS - SI

: F.P. 125

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Not Authorized
 L1 Sing &
 Purvey After Paint
 5 days

VEHICLE NO: GBF789C

MODEL: NISSAN NV200 1.5 MT

CHASSIS NO: VSKYBAM20Z0125389

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER	Ry \$ 680.00 ✓
FRONT BUMPER RETAINER LHS	Diy \$ 65.00 ✓
FRONT BUMPER RETAINER RHS	Rn \$ 65.00 X
FRONT BUMPER REINFORCEMENT	\$? 680.00
FRONT HEADLAMP LHS	CM \$ 550.00 ✓
FRONT HEADLAMP RHS	Rn \$ 550.00 X
FRONT BUMPER TOWING CAP	Rn \$ 65.00 ✓
FRONT BONNET	Ry \$ 950.00 ✓
FRONT BONNET HINGE LHS	Diy \$ 95.00 ✓
FRONT BONNET HINGE RHS	\$ 95.00 ?
FRONT GRILLE	CM \$ 580.00 ✓
FRONT EMBLEM	Rn \$ 95.00 ✓
FRONT GRILLE LOWER GARNISH	CM \$ 280.00 ✓
FRONT SUPPORT PANEL	\$ 850.00 ?
FRONT GRACE PANEL	\$ 150.00 ?
CONDENSOR	\$ 850.00 ?
RADIATOR	\$ 1,150.00 ?
RADIATOR COWLING	\$ Rn 650.00 X
FRONT FENDER LHS	\$ Rn 550.00 ✓
FRONT FENDER INNER SHIELD LHS	\$ Rn 200.00 X
	\$ 9,150.00
	10% \$ 915.00
	\$ 8,235.00
<u>SPECIAL NETT ITEMS</u>	

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FRONT CARPLATE W/HOLDER		<i>Rs</i>	<i>\$ 450</i>	60.00	
FRONT BUMPER CLIPS 1 SET		<i>Rs</i>	\$	60.00	✓
FRONT FENDER INNER SHIELD CLIPS 1 SET			<i>\$ run</i>	60.00	✓
FRONT WHEEL CAP LHS			\$	50.00	✓
FRONT WHEEL TYRE LHS			\$	300.00	✓
FRONT RIMS LHS			\$	400.00	✓
	Total		\$	930.00	
		TOTAL PARTS		\$	9,165.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ ⁵⁰⁰ 1,400.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ ⁷⁰⁰ 1,400.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ ²⁰⁰ 100.00
4	To provide anti-rust treatment on affected areas	\$ ⁶⁰⁰ 100.00
5	To remove and re-fix front aircond condenser and top up gas	\$ 200.00 ?
6	To remove and re-fix front radiator and top up coolant	\$ 200.00 ?
7	To conduct wheel alignment	\$ ⁶⁰⁰ 180.00
	Labour Total :	\$ 3,580.00
	TOTAL (PARTS & LABOUR):	\$ 12,745.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/11/2022 17:13 (SGT)
Reported by	Driver
Date of Accident	08/11/2022 07:04 (SGT)
Exact Location of Accident	Outram Park, Singapore
Additional Location Information	NEAR TO NEW OUTRAM & MRT STATION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF789C
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	C & P RENT-A-CAR PTE LTD
Company Reg No	1XXXXX477H
Email Address	claims@cartimes.com.sg
Mobile Phone No	(Phone) +65-81267188
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Nv200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	1461


INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD22V01367/VCZ/R09

DRIVER

Name of Driver	GANESAN ANBALAGAN
Work Permit No	GXXXX461T
Date Of Birth	02/05/1987
Occupation	Outdoor

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement Refer to Police Report

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Handwritten signature]





**SINGAPORE
POLICE FORCE**



T/20221108/2119

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No: T/20221108/2119

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GANESAN ANBALAGAN	ID No.	G5109461T
Related Vehicle	GBF789C (Van)	Contact No.	81267188
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: 09/08/2026
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WANG GUODONG	ID No.	G2503369N
Related Vehicle	XE4680A (Trailer)	Contact No.	86202133
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above-mentioned date, time and location, I parked my vehicle (GBF789C) along the Outram Park. I parked there as I was doing maintenance work for about 4 hours. The main contractor is namely Mr Ramesh (HP: 89292572) dedicated a spot for me to park the vehicle when conducting maintenance work.

When I was doing maintenance work, I received a call Mr Ramesh. Mr Ramesh informed me that my vehicle got hit by a trailer and my vehicle also collided with Mr Slamet (HP:96322387) vehicle (PC8445S). I then immediately and make a check on the accident.

There was damage on my left front bumper and rear bumper. There was nobody injured.

After that, police resources attended to the accident.