

ESTIMATE

LONPAC INSURANCE BHD
300 BEACH ROAD
17-04/07 THE CONCOURSE
SINGAPORE 199555

Page : 1
Veh No : SJK5147B
Model : TOYOTA CAMRY
Acc Date : 10-Nov-22
Incharge : BILLY
Code : CD0041

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 158419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U.Price	Amt \$
----	-------------	-----	---------	--------

LIST ITEMS:

1	BOOT LID <i>✓</i>	1	\$ 895.00	\$ 895.00
2	BOOT LID HINGE RH & LH <i>? Xnn</i>	2	\$ 153.00	\$ 306.00 <i>X</i>
3	BOOT LID LOGO <i>nn</i>	1	\$ 65.00	\$ 65.00
4	BOOT LID EMBLEM - CAMRY <i>nn</i>	1	\$ 58.00	\$ 58.00
5	BOOT LID EMBLEM - 2.0 <i>nn</i>	1	\$ 48.00	\$ 48.00
6	BOOT LID CHROME MOULDING <i>? Xnn</i>	1	\$ 375.00	\$ 375.00 <i>X</i>
7	BOOT LID REFLECTOR RH & LH <i>? Xnn</i> <i>1pc - nn / @395</i>	2	\$ 395.00	\$ 790.00 <i>395</i>
8	BOOT LID GARNISH <i>? nn</i>	1	\$ 502.80	\$ 502.80
9	BOOT LID LOCK <i>cut</i>	1	\$ 380.00	\$ 380.00
10	BOOT LID WEATHERSTRIP <i>nn</i>	1	\$ 225.00	\$ 225.00
11	TAILLAMP ASSY RH & LH <i>nn</i>	2	\$ 510.00	\$ 1,020.00
12	TAILLAMP PANEL RH & LH (REPAIR)	2	\$ -	\$ -
13	REAR END PANEL <i>photo. repair</i>	1	\$ 605.00	\$ 605.00 <i>X</i>
14	REAR END PANEL TOP COVER <i>nn</i>	1	\$ 400.00	\$ 400.00
15	REAR BUMPER <i>nn</i>	1	\$ 545.00	\$ 545.00
16	REAR BUMPER SCREW CAP LH <i>X nn</i>	1	\$ 55.00	\$ 55.00 <i>X</i>
17	REAR BUMPER REINFORCEMENT <i>nn</i>	1	\$ 395.00	\$ 395.00
18	REAR BUMPER RETAINER RH & LH <i>X nn</i>	2	\$ 65.00	\$ 130.00 <i>X</i>
19	REAR BUMPER CLIPS <i>nn</i>	10	\$ 5.00	\$ 50.00
LIST TOTAL S\$				\$6,844.80
25% DISCOUNT				\$ 1,711.20
				<u>\$ 5,133.60</u>

4978.80

25%

3734.10

SPECIAL NET ITEMS:

1	REVERSE SENSOR <i>nn</i>	1	\$ 200.00	\$ 200.00
SPECIAL NET TOTAL S\$				<u>\$ 200.00</u>

200

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

LABOUR

- | | | |
|---|--|----------------------------|
| 1 | TO CUT / WELD REAR END PANEL , KNOCK & STRAIGHTEN
TAILLAMP PANELS, REAR FENDERS. REMOVE & REPLACE ACCIDENT
PARTS, REALIGN ALL CONNECTION | \$ 800.00 700 |
| 2 | SPRAY RAIN T BOOT LID, REAR END PANEL, TAILLAMP PANEL,
REAR FENDERS, REAR BUMPER.SPARE WHEEL PANEL | \$ 1,000.00 600 |
| 3 | REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM,
GARNISH, COVERING | \$ 600.00 40 |
| 4 | REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION | \$ 600.00 80 |
| 5 | RUST PROOF AFFECTED AREAS | \$ 50.00 ✓ |
| | LABOUR TOTAL S\$ | <u>\$1,970.00</u> |

3734.10

200.00

1430.00

5364.10

20%

4291.28

NON-TAX AMOUNTS

GST @ 7%

AMOUNT DUE

\$7,303.60

\$511.25

\$7,814.85

L/S- \$4,300 / 6 days

Rame

Hf 90010068

6 days

L/S

21/11/22 @ 1210

Raz after paint

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: