



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/FCI22009129/Eny3-1

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: ~~CS3/FCI22009129/Eny3~~
Date: ~~16/09/2022~~ 11/11/2022
Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PC 5189B	Veh. Inspected	FBS 8681H
Policy No.		Coverage (\$)	0.00
Claim No.	D22002645MFBP	Excess (\$)	0.00
Assign From	ANN DINTE ESTHER LIM	Assign Date	16/09/2022 11/11/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/08/2022	Inspection Date	16/09/2022
Survey held at	SPEEDWAY MOTOR PL 36 TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.