



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS3/FCI22009129/Eny3e2-1 Date: 15/11/2022 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	PC 5189B	Veh. Inspected	FBS 8681H
Policy No.	D-22099590MFBP/1	Coverage (\$)	0.00
Claim No.	D22002645MFBP	Excess (\$)	0.00
Assign From	ESTHER LIM	Assign Date	11/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA FORZA	c.c	329
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MLHNF097XM5019388	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	140/70-14	BRIDGESTONE	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-15	BRIDGESTONE	4 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	21/08/2022	Inspection Date	16/09/2022
Survey held at	SPEEDWAY MOTOR PL 36 TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	