



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22004927/Rqp3e2-1	
			Date: 08/05/2023	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 6739D	Veh. Inspected	FBR 5266Z	
Policy No.	DMCVSNW00116512100	Coverage (\$)	0.00	
Claim No.	SNM22D203308/C02	Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	09/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA MX KING T150 M	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MH3UG0750LK071227	Colour	MULTI COLOUR	
Odometer	41797 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	90/80-17	DUNLOP	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/70-17	DUNLOP	3 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/05/2022	Inspection Date	25/05/2022	
Survey held at	CHEK KONG MOTOR 387B YEW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	