

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 5266Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	BENT	85.00	85.00
1	SET HANDLE BAR END	CUT	40.00	40.00
1	CLUTCH LEVER	NOT NECESSARY	28.00	-
1	BRAKE LEVER	CUT	28.00	28.00
1	SET MIRROR	BROKEN	96.00	45.00
1	FRONT COWLING COMPLETE	GRAZED	165.00	165.00
1	FRONT INNER PANEL	CUT	116.00	116.00
1	FRONT STAY	DISTORTED	65.00	65.00
1	SET FORK ASSY.	BENT	760.00	700.00
1	FORK UNDER BRACKET	BENT	165.00	165.00
1	FRONT FENDER COMPLETE	CUT	122.00	122.00
1	RADIATOR ASSY	NOT NECESSARY	415.00	-
2	FRONT SIDE COVER COMPLETE @\$148.00	O/S CUT	296.00	148.00
1	PAIR FRONT SIGNAL LIGHT	O/S CUT	112.00	112.00
1	GEAR SHIFT PEDAL	NOT NECESSARY	59.00	-
1	BRAKE PEDAL	CUT / BENT	62.00	62.00
2	REAR COVER COMPLETE @\$128.00	CUT / GRAZED	256.00	256.00
1	REAR FENDER COMPLETE	BENT	126.00	126.00
1	SET REAR FENDER BRACKET	NOT NECESSARY	42.00	-
1	MUFFLER ASSY	CUT	485.00	485.00
1	MUFFLER PROTECTOR	CUT	72.00	60.00
1	MUFFLER CAP	CUT	42.00	35.00
	LESS 10% DISCOUNT		-363.70	-281.50
			3,273.30	2,533.50
<u>SPECIAL NETT ITEMS</u>				
1	SET STEERING CONE & BEARING (SN)	NECESSARY	80.00	60.00
1	BTL RADIATOR COOLANT (SN)	NOT NECESSARY	24.00	-
			104.00	60.00
<u>LABOUR</u>				
	TOWING FEE.		80.00	60.00

Report Ref No. CS3/CTI22004927/Rqp3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPAIR BODY FRAME STEERING COLUMN.		700.00	200.00
	RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS.		450.00	300.00
	REPAIR & STRAIGHTEN SWINGARM.		300.00	100.00
			1,530.00	660.00
GRAND TOTAL			4,907.30	3,253.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00
---	--	--	----------

Report Ref No. CS3/CTI22004927/Rqp3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.