

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

INS: China Taiping Insurance (Singapore) Pte Ltd

OWNER: Golden Top Travel

Registration no. : PA 6567 Y / ISUZU LT134P

Quotation no: CM181102-1

Accident Date: 29/10/2022

Date : 7-Nov-22

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Rear bumper ✓ DD	2600 ✓ \$2,950.00
2	1	Rear Panel Inner brackets ✗ Repair	\$1,100.00
3	1	Bumper beam ✗ Repair	\$550.00
4	1	Rear tailgate ✓ DD	3550 ✓ \$3,760.00
			<u>\$8,360.00</u>
		6150	
		10%	
		-15%	
		5535	
		5227.50	
		Less 10 %	\$836.00
			<u>\$7,524.00</u>
<u>SPECIAL NETT ITEM</u>			
1	1	Sticker Logo ✓ NEC	50 ✓ \$80.00
2	1	Rear Tailgate Lock ✗ NN	\$228.00
3	1	Rear Handle ✗ NN	\$85.00
			<u>\$393.00</u>
<u>LABOUR & MISC CHARGES</u>			
1		To knock out the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	900 750 ✓ \$2,200.00
2		Supply spray paint material and necessary items to respray on the accident damage area and other affected area / panel.	950 800 ✓ \$2,200.00
3		To spray under-carriage insulation foam.	350 ✓ \$400.00
		TOTAL	1900 <u>\$4,800.00</u>
		Total Parts and Labour Cost of Repair	\$12,717.00

7485

Steve (LKK)

02/11/22

Without Prejudice

L/S

Resurvey After Spray

4 days

L/S - 5988

= 6000

