



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22011352/Kpa3q2 Date: 03/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMD 4193A	Veh. Inspected	SHC 5442P	
Policy No.	DMPCSNW00180492201	Coverage (\$)	0.00	
Claim No.	SNM22D207996	Excess (\$)	0.00	
Assign From		Assign Date	13/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JTDKB3FU203092189	Colour	M.P.WHITE/RED	
Odometer	127293 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	9 mm	
L/H Front Tyre	195/65 R15	SAILUN	9 mm	
R/H Rear Tyre	195/65 R15	LANVIGATOR	7 mm	
L/H Rear Tyre	195/65 R15	LANVIGATOR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/11/2022	Inspection Date	08/11/2022	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5442P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	BENT	332.70	332.70
1	GUARD, REAR BUMPER, CENTER	BENT	374.50	374.50
1	SEAL, REAR BUMPER SIDE, LH	NO SUCH PARTS	118.30	-
1	SEAL, REAR BUMPER SIDE, RH	NO SUCH PARTS	118.30	-
1	RETAINER, REAR BUMPER SIDE, RH	DISTORTED	132.60	132.60
1	RETAINER, REAR BUMPER SIDE, LH	DISTORTED	132.60	132.60
1	COVER, REAR BUMPER, LOWER	DENTED	22.00	22.00
1	COVER, DECK TRIM, REAR	SERVICEABLE	126.70	-
1	COVER, FLOOR UNDER, NO.2 (RH)	SERVICEABLE	241.90	-
1	COVER, FLOOR UNDER, NO.1 (LH)	SERVICEABLE	175.10	-
1	COVER, REAR FLOOR (CTR)	SERVICEABLE	229.90	-
1	PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	PANEL SUB-ASSY, BACK DOOR	BENT	1,147.80	1,147.80
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	NECESSARY	54.60	54.60
1	PLATE, BACK DOOR NAME, NO.1	NECESSARY	54.60	54.60
1	ORNAMENT SUB-ASSY, BACK DOOR	NECESSARY	47.90	47.90
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	MTG CRACKED	913.60	913.60
1	BOARD ASSY, BACK DOOR TRIM	SERVICEABLE	259.20	-
1	WEATHERSTRIP, BACK DOOR	SERVICEABLE	372.30	-
1	STAY ASSY, BACK DOOR, LH	SERVICEABLE	242.50	-
1	STAY ASSY, BACK DOOR, RH	SERVICEABLE	242.50	-
1	HINGE ASSY, BACK DOOR, LH	TO REPAIR SEE LABOUR	61.00	-
1	HINGE ASSY, BACK DOOR, RH	TO REPAIR SEE LABOUR	61.00	-
	LESS 25% DISCOUNT		-1,649.55	-924.62
			4,948.65	2,773.88
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT STICKER TRANSCAB (SN)	NECESSARY	100.00	30.00
1	BOOT STICKER TEL NO (SN)	NECESSARY	100.00	30.00
1	SET PARKING AID (SN)	DENTED	700.00	220.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	85.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
1	REAR BUMPER SIDE CLIP (SN)	NOT NECESSARY	60.00	-
			1,120.00	340.00
	LABOUR			
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BODY LOWER BACK, HINGE ASSY, BACK DOOR, LH AND HINGE ASSY, BACK DOOR, RH.		1,800.00	400.00
	TO TRANSFER FOR REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	880.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			5,300.00	1,410.00
GRAND TOTAL			11,368.65	4,523.88
RECOMMENDED COST OF REPAIRS				4,523.88

Report Ref No. CC3/CTI22011352/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 5442P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 5442P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 5442P

RE-INSPECTION

