

ASS. REC. BY:

REF: C12/ 22011352/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

1.21

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

17/11 84523.88 Car

Veh No:

SHE 5442P

Yr Regn:

04 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

127293

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU203092189

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Sailun

195/65R15

R: Ligiata

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

5/11/22

D.O.I.

8/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authorized
Mechanic B&Pain

AAD2211-

4523.88

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5442P

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 NOV 2022

SHC5442P

JTDKB3FU203092189

200303878K

TOYOTA

PRIUS GEN 4

05/11/2022

SMD4193A/ China

15/04/2021

PART	
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, LH
1	SEAL, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, LH
1	COVER, REAR BUMPER, LOWER
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO.2 (RH)
1	COVER, FLOOR UNDER, NO.1 (LH)
1	COVER, REAR FLOOR (CTR)
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, BACK DOOR
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH

LIST	
\$	Bu 485.60 ✓
\$	R1 332.70 ✓
\$	R1 374.50 ✓
\$	usp 118.30 X
\$	usp 118.30 X
\$	DR1 132.60 ✓
\$	DR1 132.60 ✓
\$	DR 22.00 ✓
\$	Sm 126.70 X
\$	Sm 241.90 X
\$	Sm 175.10 X
\$	Sm 229.90 X
\$	R 651.00 X
\$	R1 1,147.80 ✓
\$	na 54.60 ✓
\$	na 54.60 ✓
\$	na 47.90 ✓
\$	mjcat 913.60 ✓
\$	Sm 259.20 X
\$	Sm 372.30 X
\$	Sm 242.50 X
\$	Sm 242.50 X
\$	R 61.00 X
\$	R 61.00 X

TOTAL	\$	6,598.20
25%	\$	1,649.55
	\$	4,948.65

Special Nett

1 REAR BUMPER SIDE CLIP

\$ na 60.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5442P

- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER RETAINER CLIP

\$	<i>nn</i>	100.00	<i>30sn</i>
\$	<i>nn</i>	100.00	<i>30sn</i>
\$	<i>nn</i>	700.00	<i>220sn</i>
\$	<i>nn</i>	85.00	<i>60sn</i>
\$	<i>nn</i>	75.00	<i>X</i>
TOTAL		\$ 1,120.00	
TOTAL PARTS		\$ 6,068.65	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 240.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>60l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	<i>400/l</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>880l</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>50l</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20l</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL		\$ 5,300.00	

Over All Total \$ 11,368.65**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days**Days**
3 days