

SKB 3550T. 2011 May.

YSK.

Honda City 1497cc

TP Chim

MRHGM26509P020384.

Xiao Yang.

Front Number Plate	Dented	30(SN)	✓
Front Number Plate Holder	Dented	30(SN)	✓
Front Bumper	Dented	466.50	✓
Front Bumper Clips.	in	30(SN)	✓
Front Bumper Side Holder x 02	in	$24.1 \times 2 = 48.20$	✓
Front Bumper Reinforcement	Dented	215.20	✓
Front Grille	Cracked	226.70	✓
Front Grille Logo	2	28.10	✓
Front Grille Clips.	in	30(SN)	✓
Headlamp x 02	Cracked	$370.4 \times 2 = 740.80$	✓
Bonnet	Cracked	566.60	✓
Bonnet Lock.	Byd	54.90	✓

SKB 35507.

Front Support Panel	Repair	446.20. +
Front Support Panel Top Garnish		=
Front Support Panel Top Garnish Clips.		=
Air Con Condenser	Warpped	565.50 ✓
Radiator.	we are	908.20. +
Rees Number Plate	} not on	30(SN) +
Rees Number Plate Holder		30(SN) +
Rees Bumper	Distorted	463.70 ✓
Rees Bumper Clips.	} her	30(SN) ✓
Rees Bumper Side Holder x02		22.2 x 2 = 44.40 ✓
Reverse Sensor	Bad	280(SN) 200(SN)
Rees End Panel.	Dented	399.30 ✓
Rees End Panel Top Garnish.	Behind	98.20 ✓
Rees End Panel Top Garnish Clips.	her	20(SN) ✓

SKB3550T.

Rear End Panel Sealant	Per	60(SN)	✓
Tailcap x 02	Cracked	$255.3 \times 2 = 510.60$	✓
Tailcap Panel x 02	Dented	$92.4 \times 2 = 184.80$	✓
Bootlid	Dented	564.90	✓
Bootlid Lock	Per	85.40	✓
Bootlid Weatherstripe	Cut	95.90	✓
Bootlid Hinge x 02	Per	$75.2 \times 2 = 150.40$	+
Bootlid Outer Chrome.	Cracked	130.90	✓
Bootlid Key Lock.	Per	65.90	✓
Bootlid Inner Trim	Rehnd	110.40	✓
Bootlid Inner Trim Clips.	Per	30(SN)	✓
Honda Logo.	} New	39.40	✓
City Emblem.		45.90	✓
i-Vtec Emblem		50.40	✓
Rear Fender x 02	RH Buckled	$766.9 \times 2 = 1533.80$	766.90
Rear Fender Inner Trim x 02	Per	$191.3 \times 2 = 382.60$	+
Rear Fender Inner Trim Clips.	Per	60(SN)	+

SKB3550T.

Rees	Windscreen Moulding.	per	102.40	-
Rees	Windscreen Sealant		60(SN)	-
Spare Tyre Panel		Reps	715.40	+
Spare Tyre Panel Top Board.		born	142.90	✓
Spare Tyre Panel Insulator Pad.		M	200(SN)	+
Rees	Exhaust Pipe.	2	586.60	+
Rees	Exhaust Pipe Mounting.	MP	42.10.	+
Rees	Exhaust Pipe Gasket.	per	32.40.	+

6814.80

S-N: 570

5451.84

SKB 3550T.

Panel Beating	3000	2000
Spray Painting.	2500	1800
Wiring.	150	60
To spray buff coat	250	150
To remove condenser and to top up air con gas	120	60
To remove radiator and to top up coolant	120	x
To remove reverse sensor	100	50
To remove upholstery and re-seat.	280	80
To remove rear windscreen.	180	120
To remove exhaust pipe.	150	x
To transfer bootlid fittings.	150	80
		4400

total: 10371.84

L/s: 8.3k.

14 Days

(8.37k)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: