

SLW5773 G. 2018 Feb.

TPA16
Xiao To ry.

M1HFZ28H3800051216

Toyota Sienta 1496cc.

Front Bumper	Deformed	486.10. ✓
Front Bumper Lips.	new	30(SN). ✓
Front Bumper Side Holder RH.	Deformed	48.10 ✓
Front Bumper Reinforcement.	✓ XHP	330.90 ✗
Front Bumper Sponges.	✓ NEC	145.10. ✗
Front Bumper Fog Lamp RH.	cut	276.40. ✓
Front Bumper Fog Lamp Cover RH.	cut	108.50 ✓
Handlup RH.	cut	3050.10. ✓
Front RH Fender	Dented	713.20. ✓
Front RH Fender Inner Shield	Deformed	216.70. ✓
Front RH Fender Inner Shield Lips.	new	30(SN) ✓
Front RH Tyre.	all new	250(SN) ✗
Front RH Wheel Rim.	cut	880(SN) 550(SN)

SLW57739.

Sliding Door RH.	Repair	1217.50.	X
Sliding Door Protector RH.	Cut	198.80.	/
Rear RH Fender Protector RH	Cut	101.90	/
Front RH lower Arm.	Best	486.30	/
Front RH Shock Absorber	Best	407.40	/
Front RH Knuckle Arm.	Best	425.40	/
Front RH Wheel Hub c/w Bearing	Best	350.80.	/
Front RH Wheel Hub Bearing.		=	
Steering Rack and Pinion.	Ref new	2384	X

6869.70

5152.27

S.N: 610

SLW 57736.

Panel Beating

Spray Painting.

Wiring.

To spray buff coat.

To transfer sliding door fittings.

To dismantle front undercarriage.

To perform wheel alignment.

~~800~~ 650

~~800~~ 700

~~180~~ 30

~~150~~ 60

150 X

~~350~~ 220

~~150~~ 80

total: 7502.27

L/S: 6K.C.

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: