

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III22011358/KQY3E2**Date:** 20/12/2022REFERENCEInsured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02
Date of Loss: 30/10/2022 Nature of Claim: OD Claim No: MFL2022D0007218DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDV9966R**
Make & Model: MERCEDES-BENZ GLC 200, 2.0 (A) Engine No: 26492030423857
Reg. Date: 27/12/2021 (Man. Year: 2021) Chassis No: W1N2539802G003524
Colour: Metallic Silver Odometer: 7337 km
Engine Capacity: 1991 cc
Market Value/New Car Price: S\$250,000.00
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: YesCONDITION OF TYRESFront Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,947.80	7,701.30	1,246.50	13.93
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	780.00	580.00	200.00	25.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,738.80	8,292.30	1,446.50	14.85
+ GST 7.00/7.00% (S\$)	681.72	580.46	101.26	14.85
Nett Amount (S\$)	10,420.52	8,872.76	1,547.76	14.85

INSPECTIONDate of Assignment: 14/11/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected: 14/11/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701
Estimated Period of Repair: 3.0 days**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2022)
Parts: M1-SUV	MERCEDES-BENZ GLC 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDV9966R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*LEFT HEADLAMP	Cut	5,100.00 FL	*4,855.00 FL	
2	1		*FRONT BUMPER	Buckled / Cracked	1,943.00 FL	*1,943.00 FL	
3	1		*FRONT BUMPER LEFT SIDE COVER	Dented	84.00 FL	*84.00 FL	
4	1		*FRONT BUMPER LOWER GARNISH	Distorted	525.00 FL	*525.00 FL	
5	1		*FRONT BUMPER LOWER CHROME	Dented / Cut	1,650.00 FL	*1,150.00 FL	
6	1		*FRONT LEFT PARKING SENSOR 1	Not Necessary	320.00 FL	*- FL	
7	1		*FRONT LEFT PARKING SENSOR 2	Not Necessary	320.00 FL	*- FL	
					Sub Total (\$\$)	9,942.00	8,557.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	994.20	855.70
					Total Parts (\$\$)	8,947.80	7,701.30

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit Front damage parts	New	400.00	250.00
2	To putty & respray on Front bumper.	New	300.00	250.00
3	To check wiring, focus headlamp & install parking sensor	New	80.00	80.00
			Gross Labour Cost (\$\$)	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >