

Plate Number SDV9966R	Case Number -	Brand Mercedes-Benz	Model Details GLC	Body Type SUV	Insurance company INDIA INTERNATIONAL INSURANCE	Exp CS'
Technician -	SA LKK_assignments	Parts Manager -				

Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	HEADLAMP L H <input type="button" value="Customized"/>			\$0.00	\$4855.00	-10 %	1	\$4369.50
02	FRONT BUMP ER <input type="button" value="Customized"/>			\$0.00	\$1943.00	-10 %	1	\$1748.70
03	FRONT BUMP ER LEFT SIDE COVER <input type="button" value="Customized"/>			\$0.00	\$84.00	-10 %	1	\$75.60
04	FRONT BUMP ER LOWER G ARNISH <input type="button" value="Customized"/>			\$0.00	\$525.00	-10 %	1	\$472.50
05	FRONT BUMP ER LOWER C HROME <input type="button" value="Customized"/>			\$0.00	\$1150.00	-10 %	1	\$1035.00
Total :\$7701.30								

Materials

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	MSIC <input type="button" value="Customized"/>			\$0.00	\$11.00	0 %	1.0	\$11.00
Total :\$11.00								

Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS <input type="text" value="Customized"/>		RnR	0.00	\$250.00	0 %	\$250.00
02	FOCUS HEADLAMP AND RNR PARKING SENSOR <input type="text" value="Customized"/>		RnR	0.00	\$80.00	0 %	\$80.00
Total :							\$330.00

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	PAINT ON ACCIDENT AFFECTED AREAS <input type="text" value="Customized"/>		Full spray	0.00	\$250.00	0 %	\$250.00
Total :							\$250.00

Remarks 2 remarks

2022-12-19 23:10 Assessor Supervisor-Insurlogic 1 6584981566

Final review base on information provide by LKK: Concluded the cost of repair at \$8292.30 with 3 days for rep



2022-11-23 08:56 Assessor Supervisor-Insurlogic 1 6584981566

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic

Amount : \$8871.80

Check: \$656.00

Repair Duration: 3 days

