

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 08 Feb 2023

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------------|
| Vehicle No | : GBK7775U | Accident Date | : 07/11/2022 |
| Make | : TOYOTA HIACE | Policy No. | : DMCVSNW00138232101 |
| Assignment Date | : 14/11/2022 | Excess | : S\$1,500.00 |
| Date of Inspection | : 14/11/2022 | Est. Duration of Repair | : 18 |
| Inspection At | : DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | | |
|-----------------------------|------|-----------|--|
| Repairer's Estimate (Gross) | :S\$ | 30,444.49 | (Estimate \$28,329.49 + Supplementary \$2,115.00) |
| Revised Amount | :S\$ | 16,254.57 | |
| Check Items (Estimated) | :S\$ | 7,625.00 | |
| Total | :S\$ | 23,879.57 | |
| Lump Sum Repair | :S\$ | | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 84,000.00 |
| COE / PARF Rebate | :S\$ | 21,483.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 62,517.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.